

- Non-normal distributions, *continued*
(See Skewed distributions; Bimodal distributions; Multimodal distributions; Symmetrical non-normal distributions)
- Non-normal sampling distributions, 132, 138, 182-183, 191, 239, 242
- Non-random arrangement of points on a control chart, 36, 55-56, 72-73, 75, 99, 108-109, 149
(See Grouping or bunching)
- Non-randomness
in haphazard data, 116
in measurements, 116, 165-166
in patterns, 24-25, 149, 153, 156, 160, 161, 165, 172, 173, 175, 176-177
in sampling, 167, 171, 173, 180, 214, 239
- Non-standard control charts, 198
- Normal capacity, losses, yields etc., 35, 45, 46, 54
- Normal distribution
assumption of, 78, 80, 82-83, 88, 124-125, 127, 154
behavior of samples from, 156
compared with specification, 30-31, 58-59, 119-121, 132-133
description of, 131-134
equation for, 132
estimating percentages for, 30-31, 58-59, 132-133
estimating spread of, 56, 71, 119-120, 122
fitting data to, 139-141
importance of, 78, 80, 82-83, 88, 124-125, 126-127, 132, 138
"modified" limits for, on a shop chart, 195-196
not necessarily desirable, 57
not necessarily present in the case of a natural pattern, 170
of errors, 88
probabilities associated with, 132-133, 180-182
sampling distributions from, 138, 181, 182
tables for, 133
tests for, 78-79, 83, 133-134
theoretical description of, 131-134, 139-141
- Normal inspection
as an inspection level, 246, 264, 273-274
as normal amount of detailing etc., 46, 120-121, 226, 233-236, 246, 254-255, 256, 257, 263, 265
- Normality
assumption of, 78, 80, 82, 83, 88, 124-125, 127, 154
hypothesis of, 82
(See Normal distribution)
- Normal lot size, 262
- Normal product
accepted by a sampling plan, 233, 244, 255, 264, 265, 273, 274
rejected by a sampling plan, 246, 254-255, 265, 273
(See Process average; Process capability)
(See also OC curves)
- Notes
by a machine setter, 66, 67, 213, 217
recorded in a process capability study, 49, 51, 53, 66, 67, 70, 71
recorded on a shop chart, 206, 208, 209, 212, 213, 215, 217, 218, 221, 227
- np , 20
- np -Charts, 20, 160, 191, 229
- Number
of a gage, test set etc., 49
of a machine or shift, 49, 207
of causes affecting one chart, 190
of characteristics covered by inspection, 265, 270
of characteristics covered on a p -chart or c -chart, 17, 48, 59, 157, 159, 160, 189, 190, 196
of characteristics covered on a sampling plan, 263
of charts, 34, 38, 41, 72, 187, 189, 190, 199, 219, 223, 225, 226, 227
of complaints, 38, 62, 226, 246, 264
of defects, 20-21, 46, 191, 206, 233, 236, 239, 240, 265
of defects missed by 100% inspection, 236
of defects per unit (as an inspection requirement), 265
of inspection items, 263, 265, 270
of inspectors, 23, 38, 226
of jobs on sampling inspection, 226, 233-236
of jobs under process control, 226
of measurements in an experiment, 77-78, 84-85, 90, 93, 110, 111, 113 (See Amount of data)
of measurements in a process capability study, 50, 66-72
of operations, 225
of operations charted, 190, 225, 226
of operations not requiring process control, 190, 225
of operations still to be studied, 225
of operations studied, 225, 226
of operators, 23, 38, 71, 226
of operators working with process control, 226
of process control charts (See Number of charts)
of samples taken in a process capability study, 66
- Number of units
in a sample, 12, 17, 18, 19, 20, 50-51, 66, 83, 84, 85, 98, 107, 111, 160, 189, 191 (See Sample size)
in an experiment, 78-80, 84, 85, 91-93, 110, 113, 116
- Numbers in general, 3, 4, 5, 6
- Numerical effects in data, 75, 94-97, 99, 100, 102-106
- O**
- Objectives
in separating data, 36, 55, 59, 75, 157, 159, 218-219
of a cost reduction case, 226
of a quality control program, vii, 3-4, 10, 33-41, 45-47, 53-54, 61-63, 71-72, 75, 77, 119, 122, 125-126, 169, 187-189, 201-203, 217-226, 233-236, 273-274
of designed experiments, 4, 34, 36, 62, 75-77, 84, 91, 92, 101, 112-113, 219, 220
of inspection, 38-39, 233-236, 264, 273-274
of process capability studies, 34-36, 45-47, 66, 72, 159, 187, 221
of process control charts, 10, 36-38, 62, 63-64, 125, 187-189, 190, 201-206, 224, 225-226, 233, 262, 265, 273-274
of the Quality control team, 33, 39-41, 45-47, 66, 75, 187, 223-226, 236, 274
- Obscure patterns (in a process capability study), 66, 67
- Observational standards, 268
- Observations (See Measurements Data)
- Observed average, frequency etc., 78
- Observed data
informal analysis of, 5, 6, 9, 78
theoretical distribution fitted to, 139-141
- Observers, 50
- Obsolete shop charts, 41, 199, 219, 223, 227
- Obtaining data
cost of, 17, 47-48, 116, 188, 189
difficulty of, 17, 47, 188, 189
for experiments, 76, 77, 84, 85, 91-92, 93, 113-117

- for performance studies, 74, 188, 228
- for process capability studies, 47-51, 55, 63-64, 66-67, 223, 228
- for shop charts, 41, 190-192, 205-210, 213-215, 223, 228
- Obvious defects, 209, 269
- Occasional checks, 190, 224
- Occasional disturbance in a process, 16, 51, 53, 67, 150, 203-204
(See Overadjustment)
- OC curves
 - as basis for selecting sampling plans, 242-246, 247, 249, 252, 254-255, 256, 264, 265
 - compared to process, 244, 255, 264, 265
 - costs associated with, 245-246
 - economic importance of, 242-246, 254-255, 264-265
 - examples of, 239, 243, 246, 249, 252, 256
 - explanation of, 238-239, 239-242, 242-246
 - for continuous sampling, 241, 256
 - for single, double and multiple sampling, 239-242, 243, 244-255
 - for variables sampling, 242
 - importance of, 242-246, 255, 264, 265
 - plotting of, 240-241
 - used in comparing sampling plans, 242-245, 246, 249, 252, 256, 260
 - uses for, in estimating risks, 244-245
- Odd points in a test, 26, 181
- Offcenter
 - contacts on a relay, 19
 - distributions, 62, 64, 121, 160, 167, 220
 - parts, assemblies etc., 5, 8, 155, 167, 175, 180
- Offcenter processes
 - as shown on a chart for individual measurements, 160
 - deliberately run close to one side of specification, 64, 220
 - effect of, on yields, 62, 64, 121
 - in trouble with specification, 31, 62-63, 64, 121, 122
- Official quality rates, 264, 270, 273
- Ohms, 119
- Oil, 216, 270
- Olmstead, P. S., 277
- Omission
 - of operation, 163, 180, 270
 - of \bar{x} 's, 23, 218
- "One best place" (for a distribution), 193
- One factor experiment, 76
- One hundred percent
 - gaging by shop, 72
 - good or bad (said of product), 173, 180, 190
 - inspection, 46, 188, 190, 226, 233-236, 249-251, 254, 256, 257, 263, 265
 - sorting, 46, 71-72, 120-122, 190, 191, 226, 235, 246, 252, 255, 257, 263, 265
- One percent limits, 97, 99, 100, 107, 109
- One-sided
 - process, 62, 64, 121, 160, 220
 - tests, 28, 182
- One year report, 225
- "Opens," 209
- Operate current, 66-71
- Operating organization
 - action by, on control charts, 16, 19, 202, 203-204, 217-219, 221
 - cooperation of, with Engineering, 33, 38, 39-41, 45, 65, 74, 188, 190, 202, 219, 220, 223, 224, 226
 - emphasis on, vii, 187, 201, 216
 - problems of, 3, 4, 10, 15, 19, 22-23, 33-38, 40, 46-47, 61, 62, 63-65, 66-73, 91, 101, 120-127, 151, 168, 187-226, 234-236, 246, 254-255, 260-265, 273-274
 - rejection of product to, 4, 37, 46, 66, 71, 226, 227, 237, 244-246, 254-257, 261, 263, 265, 269
 - relations of, with Inspection, 37, 38-39, 126, 187, 201, 202, 233-236, 246, 257, 260-262, 269
 - responsibility of, for plotting charts, 36, 41, 65, 187, 192, 197, 201, 205-216, 217, 219, 221, 223, 227, 228, 234
 - responsibility of, for quality, 233-236
 - responsibility of, for results, 46, 48, 188, 201, 203, 216, 217, 235
 - routines in, 33, 38, 65, 77, 202, 220, 246 (See Bottlenecks)
 - should not aim at AOQL, 254-255
 - sorting by, 46, 120-122, 226, 234-236, 246, 254-257, 260, 263, 265
(See Shop experience; Shop troubles)
- Operating supervisors, vii, 4, 5, 23, 33, 38, 39-41, 162, 168-169, 201-226, 236
- Operational sorting
(See Sorting)
- Operations
 - breakdown by, 33, 36, 55, 166, 224-225
 - categories for, 225
 - continuity of, in the shop, 36, 46, 187, 202, 217, 219
 - definition of, 225
 - difficult, 34, 47
 - effect of, on other operations, 187, 202 (See Early operations; Subsequent operations)
 - expensive, 34, 47, 71-72, 122, 235, 265
 - found to be free from trouble, 264
 - nature of, in the shop, 38, 46, 47, 190, 224, 225
 - number of, in the shop, 224, 225
 - sequence of, 209, 267
 - shortcuts in, 57, 70
 - studied and charted, 190, 224-226
- Operations research, 40, 77, 277
- Operators
 - acting as process checkers, 190, 213
 - acting on control charts, 4, 155, 158, 164, 167, 177, 178, 188, 203, 221, 235, 265
 - advantages of quality control for, 201, 202, 203
 - as a variable, 5, 6, 17, 30, 36, 55, 62, 69, 72, 73, 152, 171, 172, 178, 202, 214, 215, 217
 - capability of, 35, 46, 73, 170
 - charts for, 201-203, 221-222
 - comparison of, 36, 49, 55, 159, 171, 175, 204, 215, 218
 - control by, 30, 48, 57, 70, 188, 203
 - covered by process control, 226
 - encouragement of, 4, 33, 174, 188, 201-203, 223, 226
 - equipment given to, 155, 158, 164, 167, 169, 174, 175, 176, 179, 180, 203, 217, 218
 - experience of, 6, 73, 158, 164
(See Training)
 - explanation of control charts to, 201-202, 223, 226
 - habits of (See Work habits)
 - importance of, 38, 201, 202, 203-204, 223, 226
 - instruction of, 37, 158, 202, 212, 217, 219
 - meetings with, 201-202, 223, 226
 - motivation of, 174, 188, 201, 202, 223
 - names of, for identifying data, 49, 207, 218, 271
 - number of, required for building product, 23, 38, 71, 226
 - of an instrument, 87, 88, 89
 - sorting by, 122, 234, 235, 246, 257, 260, 263, 265
 - training of, 31, 35, 37, 46, 55, 70, 72, 73, 155, 158, 162, 164, 167, 168, 169, 175, 180, 202, 203, 204, 212, 217, 219

Opportunities
 for cost reduction, 34, 36, 46-47, 54, 187-188, 226
 for finding defects, 20
 for improvement, 35-36, 54-56, 66-71, 76, 120-121, 220, 226
Optimum
 balance between cost and quality (See Balance; Economic stopping point)
 level for a process, 37, 62, 64, 120-121, 188, 193, 264-265
 number of control charts, 34, 38, 41, 62, 63, 189, 199, 219, 223
Optional calculations, 49, 53, 98, 110
Order
 absence of, in a natural pattern, 7, 24, 149, 160, 161-162, 175, 176 (See Arrangement)
 of measurement, 78, 82, 83, 84, 85
 of plotting, in experiments, 82-83, 84, 85, 99, 108-109
 of production or testing, 5-6, 15, 49, 61, 66, 82, 84-85, 151, 176, 192, 207, 214 (See Sequence)
Orders (for work done etc.), 40
Ordinary
 control limits, on a *p*-chart, 19
 variables, 37-38, 61, 62, 71, 150-151, 217 (See Shop-type variables)
Oscillator, 90
Other departments, 223, 224 (See Suppliers)
Ott, E. R., 101, 113, 262, 277
Outer control limits, 99, 107-109
Outer third of a control chart, 25, 27, 181-183, 208
"Out of control"
 examples of, 9, 10, 15-16, 19, 37, 59-61, 66-71, 72-73, 82-83, 87-89, 99-100, 196-197, 203, 204, 206, 212-213
 good or bad? 6, 35-36, 54-56, 150-151, 189-190
 importance of, 35-36, 37-38, 45, 52-53, 54-56, 61, 74, 91, 111, 113, 122, 131, 141, 145, 189-190, 196-197, 217-219, 221, 223, 227, 262-263, 273-274
 meaning of, 9, 25-28, 30-31, 37, 63, 65, 66, 72, 74, 83, 87, 89, 100-101, 116-117, 149-151, 159, 160, 172, 189-190, 217-219, 220-221, 222
 synonymous with trouble, 189, 190, 223
 tests for, 23-30, 79, 180-183, 192, 208-209, 215, 218, 227, 229
Out of limits, 37, 46, 54, 56, 66, 71, 121, 160, 189, 204-206, 254 (See Percentage)
Out of order, 156, 171, 180

Out of parallel, 198
Out of round, 89-90, 198
Out of specification
 (See Out of limits)
Out-of-the-ordinary, 150
Output, 4, 10, 33-38, 46-47, 62, 64, 66, 71, 91, 101, 122, 187-189, 198, 202, 203, 217-219, 220, 224, 225, 235, 255
 (See Quantity; Production; Efficiency)
"Outside limit" material, 254, 269
Outstanding causes, 38, 63, 70, 190
Oven, 47, 55, 102, 104, 114, 152
Overadjustment, 16, 67, 166, 180, 188, 190, 203-204

Overall
 capability, 46, 48, 59, 157, 159
 cost of control charts, 10, 34, 35, 38, 62, 225-226
 estimates, 47, 48, 59
p-chart, 17, 48, 59, 157, 159, 188-189, 190, 196-197, 198, 218
 quality standards, 264, 270, 273
 savings, 10, 33-34, 38, 46-47, 225-226 (See Cost reduction)
 shifts and trends, 196-197
Overhauling of machines, gages etc., 16, 53, 113, 219
 (See Maintenance)
Overlapping tolerances, 54, 124-126, 188
Oversize parts, 71, 155, 214

P

p, 17, 18
Pairs
 alternate (See Alternate pairs)
 measurements occurring in, 160
 of measurements, used in analysis, 83, 85, 108, 109
 successive (See Successive pairs)
Panels, wired, 72, 73, 191
Pans, 167, 171, 214
Paper
 and pencil, in the shop, 215
 graph, 13, 17, 22, 79, 133, 211, 215
 improvements on, 187
 probability (See Probability paper)
 products, 20
Parameters of a product
 (See Characteristics)
Parent distribution
 as related to sampling distribution of averages, 16, 30-31, 138
 as related to various other sampling distributions, 138, 181, 182

information on, 6, 16, 53-54, 56, 61, 119-120, 122, 131, 137, 138-139, 141, 170 (See also, appropriate portions of pages 161-180)
 (See Universe; Individuals)
Parent population
 (See Parent distribution)
Part numbers, 196, 209, 269, 270
Parts
 alignment of, 5, 8, 19, 68, 69, 155, 167, 175, 180
 positioning of, 68, 69, 167, 175, 176, 180
 (See Piece parts)
Patterns
 analysis of, 9, 11, 23-32, 34-37, 52-56, 62, 66-73, 82-84, 87, 89, 100-101, 107, 109, 111-112, 116-117, 149-183, 189-190, 199, 203-206, 208-209, 212-219, 223-224, 227, 229, 237-238
 apparently worse than others, 67
 as source of assurance, 9, 274
 breakdown of, 36, 55, 66-68, 72, 166
 changes in, 55, 66-72, 73, 153, 155, 164-165, 166, 168, 174-175, 177-179, 203, 206, 218
 complex, 54, 67, 72 (See Complex patterns)
 continuous movement of, 9, 29, 160 (See Trends)
 edge of, 24-25, 29, 160, 169, 171, 172-174
 erratic, 8, 19, 31, 54-56, 60, 67, 68, 72, 162-163, 166, 169, 179-180, 204, 206
 fluctuating, 5-6, 7-9, 24, 66, 72, 160, 175, 176, 178, 190, 219, 237-238
 hidden, 67-68, 75, 218
 importance of, 4, 6, 9, 11, 35-36, 39, 45, 47, 53-56, 60, 61, 66-73, 74, 83, 87-89, 91, 97, 99-101, 144, 145, 149-180, 203-206, 215, 218, 219, 221, 223
 inconclusive, 28, 62, 64, 112, 146
 in control, 9, 35, 36, 38, 45, 47, 53-54, 58, 59, 61, 71, 74, 91, 119-122, 127, 131, 141, 149-151, 159, 170-171, 187, 188, 189, 190, 195-196, 205, 221
 information from, 4, 11, 15-16, 19-20, 35-36, 37, 53-56, 66-73, 83, 87, 89, 97, 100-101, 152-180, 189, 217-219, 221
 interpretation of, in designed experiments, 82-83, 84, 87, 89, 100-101, 107, 109, 111-112, 116-117
 interpretation of, in process capability studies, 35-36, 52-56, 59-60, 62, 66-73, 171

- interpretation of, on shop charts, 37-38, 41, 63, 65, 171, 190, 192, 194-195, 199, 201-216, 217-219, 221, 222, 223-224, 227
- interrupted, 60, 194
- length of lines in, 160, 169
- list of, 11, 54, 161
- marking of (*See* Markings on control charts; Marking x 's)
- middle of, 24-25, 29, 160, 169, 171, 172, 173, 174
- natural (*See* Natural pattern)
- non-random, in data, 24-25, 116, 149, 153, 156, 160, 161, 165-166, 172-173, 175, 176, 177
- obscure, 66-67
- of instability, 11, 25-28, 54, 68-69, 72, 83, 87-89, 161, 166-167, 179-180
- out of control, 9, 10, 15-16, 19, 25-32, 35-38, 52-53, 54-56, 59-61, 63, 65, 66-73, 74, 79, 82-83, 87-89, 91, 99-101, 111, 113, 116-117, 122, 131, 141, 145, 149-151, 159, 160, 172, 189-190, 192, 196-197, 203, 204, 206, 208-209, 212-213, 215, 217-219, 220-222, 223, 227, 229, 237-238, 262-263, 274
- produced by unnatural variation, 6, 9, 35, 54-56, 159, 218, 221
- reading of, 66-67, 69
- recognition of, 11, 54, 66-70, 161, 213, 218-219
- repetition of, 29, 69, 84-85, 156, 160, 161, 175, 176-177
- shift in, 11, 54, 55, 72, 152, 161, 164-165, 173, 174-175, 177-179
- significant, on a control chart, 35, 54-56, 60, 66-73, 75-76, 82, 87, 88, 99, 149-180, 203-206, 212, 217-219, 220, 221
- simplification of, 17, 36, 38, 48-49, 53, 54-56, 59, 63, 66-73, 75, 106, 157-160, 166-167, 179, 190, 197, 199, 218-219, 221-222, 223
- tests for, 9, 23-30, 100, 107, 109, 180-183, 208
- types of, 6, 11, 23, 54, 152-160, 161
- uninterpretable, 17, 48, 49, 59, 66-67, 72, 157, 159, 190, 219
- unnatural (*See* Unnatural patterns)
- used by Inspection, 39, 262-263, 274
- (*See* Control chart patterns; Tests for unnatural patterns)
- Pay group, 22, 203, 222
- p*-Charts**
- advantages of, 11, 17, 19-20, 48, 59, 157, 188-189, 196-197
- amount of data required for (in engineering studies), 28, 50-51, 113, 191
- as one of the measures of process capability, 45, 54, 56, 59, 62, 157
- assignable causes on, 11, 159, 189, 190, 218
- breakdown of, 48, 59, 157, 159, 190
- calculations for, 7-8, 17-18, 20, 162, 196-197, 215, 229
- centerlines for, in the shop, 62, 63, 192, 193-195, 197
- characteristics to be plotted on, 11, 17, 48-49, 59, 157-159, 189, 190
- compared with *np*-charts, *c*-charts and *u*-charts, 11, 20-21, 31, 49, 160, 189, 191
- comparisons between, 51, 159
- complex patterns on, 17, 48, 59, 73, 157, 159, 190, 198, 218, 223
- components of, 59, 157, 159
- construction of, 7-8, 17-18, 20, 196-197
- control limits for, 7-8, 17-19, 191, 194-195, 196-197, 229
- data sheets for, 207, 209, 210
- difficulty in interpreting, 11, 17, 48, 59, 72, 157-159, 190, 198, 218
- economic stopping point for, 194
- examples of, 7-8, 18-20, 51, 74, 144, 194, 204
- explanation of, 7-8, 11, 17, 48, 157-159, 188-189
- frequent defects on, 159
- importance of, 11, 45, 48, 54, 56, 59, 158-159, 196, 198
- in engineering studies, 48-49, 50, 51, 54, 59, 62, 73, 157-159
- instability on, 159, 167, 180, 194
- interpretation of (*See* Interpretation)
- levels on, 62, 194, 228
- lower limit for, 17, 18, 20, 194-195
- measurements for, 17, 18, 50, 157, 203-204, 209
- modified limits for, 196-197
- overall, 48, 59, 159, 197
- samples for, in the shop, 191
- sample size for, 17, 50, 113, 191
- scales on, 17, 51, 53, 159
- sensitivity of, 11, 48-49, 59, 158, 159
- stairstep limits for, 18-19
- stratification on, 157, 173
- substitutes for, 11, 49-50, 113, 198, 218
- symbols for, 17
- tests for, when control limits are unsymmetrical, 28, 182, 183, 191
- theory of, 137, 151
- used for correlation, 144
- used in designed experiments, 113
- used in routine inspection, 262-263
- use of decimals in calculating, 18, 20
- uses in the shop, 62, 63, 64, 188-189, 190, 194, 196-197, 204, 227
- variations of, 11, 20-21, 49, 160, 189, 191, 198, 204
- varying sample sizes for, 18, 191
- where to use, 48-49, 188-189, 191
- Peaks**
- in a cycle, 69-70, 161, 162
- in a distribution, 131, 136, 153, 155, 158, 162, 163, 165, 166, 169, 170, 173, 174, 176, 179
- Pearson, E. S., 275, 277
- Peculiarities in a distribution, 16, 140-141, 156, 160, 161
- Pencil and paper (in the shop), 215
- People in the shop, 201, 202, 203, 217 (*See* Operators; Layout operators; Machine setters; Supervisors)
- Percent**
- good, lost, spoiled etc., 11, 17, 38, 48, 157, 189
- of product rejected, 37, 46, 66, 71, 226, 227, 235, 237-239, 244-246, 254-255, 264, 265 (*See* OC Curves)
- Percentage**
- as a measure of capability, 45, 48, 54, 56, 59, 127, 157, 159, 194, 197
- as a statistic, 137, 151, 196, 198
- calculation of, 17, 18, 213
- data, 5, 11, 17-20, 31, 48, 50, 54, 59, 113, 157, 183, 188-189, 191, 194, 196-197, 198, 229
- defective (*See* Percent defective)
- determined by process capability studies, 54, 56, 58-59, 71, 126-127, 235
- differences in, 31, 159
- for non-normal distribution, 30-31, 56, 59, 134-136
- for normal distribution, 30-31, 54, 58-59, 132-133
- from an \bar{X} and *R* chart, 56, 58-59, 126-127
- from a *p*-chart, 56, 59, 157, 159
- of defectives, 11, 17, 59, 157, 189, 235, 237-265
- of dropouts, 38, 48, 189, 225, 227, 264

- Percentage, *continued*
of points out of control, 221-222, 226
of product outside of limits, 30-31, 54, 56, 58-59, 61, 64, 66, 71, 120-121, 127, 132-136, 189, 204, 225, 234-235
- Percent defective
as an inspection requirement, 265
calculation of, 17, 18, 215, 229
in a process, 61, 63, 66, 71, 127, 235
in inspection, 39, 234-235, 237, 238, 239, 243, 254-255, 263-265
in inspection planning, 244, 255, 264, 265
on a *p*-chart, 8, 11, 59, 63, 74, 157, 159, 189, 194, 215, 227
reduction of, 19, 31, 159, 167, 175, 178-179, 224-225, 233-235, 236, 265
related to operational sorting, 120, 121, 122, 235, 236, 265
- Performance
as distinguished from capability, 45, 61, 66, 74, 187-188
current, 39, 227, 264 (*See* Process average)
of a machine, 16, 19, 66, 71, 83, 202, 203, 204
on shop charts, 65, 74, 194, 206, 212-213
in the past, 61, 65
study of, to keep shop charts up to date, 74, 227, 228
(*See* Capability)
- Performance studies, 34, 74, 187, 188, 227, 228
- Periodic
adjustment of a process, 16, 67, 203
control chart audits, 227
disturbance in a process, 67, 150, 203-204 (*See* Overadjustment)
follow-up on audits, 227
patterns (*See* Cycles; Systematic variables)
review of cost reduction cases, 224, 226
review of layouts, 227
review of progress, 33, 41, 226
selections from shop control charts, 229
summaries of results, 33, 74, 221-222, 226, 228-229
- Periods of trouble, 187, 202, 233, 246, 273
- Permanent
control of process, 62, 224, 226
cost reduction, obtained by control charts, 36, 38, 226
effect of process changes, 62, 72, 228
- file of charts, 228
location of process, 62, 121, 228
results of engineering work, 38, 61, 62, 63-64, 101, 112, 187, 220
- Permissible average
as basis for choice of sampling plans in inspection, 264
as basis for shop control charts, 64, 65, 193-194, 195-196, 196-197
- Personal injury, 234
- Personnel, changes in, 227 (*See* New operators)
- Physical
abnormalities, 52, 116-117, 163, 209, 214, 268, 269
differences between units, 214, 268
laws, 6, 7
limits of materials, 57
measurements, 6
- Piece parts
abnormal, 156, 214 (*See* Set-up parts)
as a variable, 10, 31, 55, 64, 71, 167, 171, 196, 202, 212, 213, 215, 217, 220
difficulty in making, 15
ends or sides of, 90
needed for assembly, 220, 246, 260-261
positioning of (*See* Positioning)
positions on, 90 (*See* Taper; Out of round; Positional variability)
quality of, 37, 39, 47, 64, 71-72, 155, 169, 175, 180, 202, 217, 219, 220, 264
specifications for, 119
suppliers of, 174, 207, 260
- Piece rates, 203, 260, 263
(*See* Efficiency; Wage incentives)
- Pileup of metal, 209
- Pillars, walls etc., 192
- Pilot runs, 46, 76-77, 91-92, 220
- Pin projection, 123
- Pipes, 192
- Planned experiments, 76-77
(*See* Designed experiments)
- Planning
for a process capability study, 46-51, 66
for inspection, 233-236, 263, 264-265, 273, 274
for process control, 61, 62, 63-65, 187-199, 265
of quality control program, 33, 39-41, 223-226
of shop charts, 36-38, 40-41, 187-189, 190, 192, 223-224
- Plate current, 229
- Plates (for assembly, lapping etc.), 167, 212
- Plating
as a variable, 4, 35, 37, 152, 156
solutions for, 23, 153, 178
thickness of, 91, 93, 100, 101
(*See* Chemical operations)
- Platykurtic distributions
(*See* Symmetrical non-normal distributions)
- Play (in a fixture etc.), 55, 69, 155, 162, 167, 180, 219, 235
- Plotting
diagrams for, 99, 108, 109
errors in, 163, 166, 180, 219, 227, 228-229
guides for, in an experiment, 99, 109
of charts used by inspectors, 39, 262-263, 270, 274
of control charts in general, 5-6, 13-14, 18-19, 20, 21, 22, 143-144, 145, 149
of designed experiments, 82-83, 84-85, 87-88, 97, 98-100, 107-111, 116-117, 229
of process capability studies, 51-52, 53, 66-72, 72-73
of shop charts, 190, 192, 197, 201, 208-209, 213, 214-216, 219, 223, 227, 228-229
of verification samples on shop charts, 274
order of, in a designed experiment, 84-85, 99, 109
- Plotting guides
for use by statistical clerks, 229
for use in designed experiments, 99, 108, 109
- Plus or minus tolerances, 119, 122, 202
(*See* Limits)
- Points
calculation of, for an experiment, 85-86, 108-109
considered as part of a statistical pattern, 24, 149, 175, 176, 177, 274
for selecting samples, 51, 190-192, 207, 227, 267
out of control, 70, 71, 212, 213, 221-222, 226, 227
plotted by inspectors on shop charts, 274
plotting of, on control charts (*See* Plotting)
- Point-to-point correlation, 16, 29, 69-70, 156, 176-177
- Poisson distribution, 239-240, 242, 252, 277
- Pole piece assembly, 125
- Pooling
of effects with residual, 96-97, 106
of job knowledge (*See* Quality control teams)
of residual, 96-97, 106, 110-111

- Population**, 137
(*See* Parent distribution)
- Positional variability**, 89-90
- Positioning of parts**, 69, 167, 175, 176, 180, 213
- Positions**
on a machine, 55, 70, 151, 161, 172, 176, 207
on a part, 90
- Positive**
correlation (*See* Correlation)
skewness (*See* Skewness)
stop on a machine, 57
- Possible causes**, 69, 161-180, 218-219
- Potential**
effects in an experiment, 95-97, 98
electrical, 164
improvement, 35-36, 54-56, 66-71, 76, 120-121, 220, 226
- Powder**, 189
- Power**
in the hands of Inspection, 273, 274
of a control chart, 9, 11, 61, 83-84, 141, 149 (*See* Sensitivity)
of a designed experiment, 76, 112
of an instrument, 87, 88, 89
of a sampling plan, 242, 246
output, 164, 177
supply, 48
- Practical wisdom**, 40, 64, 114, 219
(*See* Job knowledge)
- Practices**
of Inspection, 233-236, 264-265, 267-271, 273-274
of Inspection (affecting Operating), 236, 246, 254-255, 263, 265
questionable, 45, 61, 73
- Precision**
in detecting out-of-control conditions, 11, 47, 48, 160, 161, 165, 189
of control limits, 52, 100, 107, 109, 161
of tests for unnatural patterns, 180-183
- Precision of measurement**, 49, 50, 61, 62, 75, 84-91, 113
(*See* Error, Compare with accuracy of measurement)
- Predictability**
as one of the concepts associated with a natural pattern, 59-61, 150, 170-171
of a distribution, 6-7, 141
of a process, 34, 35, 36, 45-46, 53-54, 64, 71
of points on a control chart, 7, 24, 149, 161, 175, 176
of results, 40, 53-54, 61-63, 71, 194
- Predictions**
engineering, 34, 35, 36, 38, 46-47, 50, 53-56, 59-61, 62, 63-64, 71, 73, 91, 101, 112, 122, 125-127, 236, 244, 265, 274
from an unnatural pattern, 35, 54-56, 59-61, 194
should properly be based on a natural pattern, 36, 53-54, 59-61, 149-150, 170, 171
statistical, 7, 24, 149-150, 170-171
(*See* Allowances; Forecasts; Estimates; Standards)
- Pressures**
due to work loads, 227
for production, 73, 155
of gas etc., considered as a process variable, 6, 11, 21, 114, 164, 189
- Prevention**
of defects, 37-38, 233, 265
of shop troubles, 33-34, 36-38, 187, 202-206
- Previous knowledge**
contradicted, 10, 68, 76
needed for interpreting patterns
(*See* Job knowledge)
reconciled with results, 77, 218
- Pride**
in improvement of job, 202, 203, 223, 226
of operators, in control charts, 203
- Prior operations**
(*See* Early operations)
- Probabilities**
associated with multiple tests, 25
(footnote), 180-183
associated with normal distribution, 31, 132-133, 181
associated with *R* charts, 137, 151, 181, 182
associated with sampling plans, 38, 237-242
associated with skewed distributions 135-136, 183
associated with various control chart tests, 183
associated with \bar{X} charts, 137-138, 151, 180-182
- Binomial**, 183, 239, 242, 252, 278
calculation of, in control chart tests, 180-183
for ranges of samples of 2: 181-183
- Hypergeometric**, 239, 242
- Poisson**, 183, 239-242, 252
tables of, 239, 242, 277, 278
used in tests for unnatural patterns, 25, 25 (footnote), 181, 183
- Probability**
limits (*See* Statistical limits)
paper, 79, 133
theory of, 237, 239-240
- Probability of acceptance**
calculation of, 239-242
examples of, 237-238, 240-242, 244-245
explanation of, 237-238, 240, 244-245
for other than single sampling plans, 242
- Probability of rejection**, 239, 240, 244-245
- Problems**
engineering (*See* Engineering problems)
isolated, 15, 19, 33, 66, 72, 125-127, 143-146, 187-189, 203-206
lists of, 3, 10, 33, 34, 46-47, 112, 114, 187
shop (*See* Operating organization, problems of)
solved by process capability studies, 4, 10, 34, 36, 46, 47, 63, 66-72, 72-73, 75-76, 112, 187-188, 220, 235, 265
solved by quality control program, 3, 4, 5, 10, 33, 34, 35, 38, 46-47, 75, 77, 187, 233-236, 265, 273-274
solved by shop charts, 10, 16, 19, 36-38, 62, 64-65, 71-72, 187-189, 202-206, 220, 221, 223-226, 235, 265
solved by studying *R* chart, 66-68
- Procedures**
as a variable, 61, 114, 158, 162, 167, 171, 178, 180, 218-219, 224, 227
in designed experiments, 78-81, 82-83, 84, 85-89, 91-92, 93-97, 97-101, 107-112, 112-117
in process capability studies, 36, 41, 45, 47-63, 63-65, 66-72, 74, 75, 112, 220, 228
in process checking, 41, 190-192, 201, 205-216, 217, 223, 227-229
in sampling inspection, 267-271
in setting up shop charts, 64, 65, 190-192, 209
unsystematic, 171, 180
- Process**
action on, in a process capability study, 36, 61-63, 66-72
adjustment of, 30, 37, 67, 153, 188, 202, 203-204, 265
centering of, 30, 62, 64-65, 120-121, 167, 170, 188, 202, 220
changes in (*See* Changes)
checked for unstable mixtures, 68, 166
compared to OC curve, 244, 255, 264, 265
control of, 217, 226 (*See* Process control)
definition of, 3-4, 45

Process, *continued*

drift of, 67, 90, 153, 175
fluctuations of (*See* Fluctuations)
immediate check on, 37, 190, 212-213, 217
improvement of (*See* Improvement)
manually controlled, 3, 16, 30, 57, 70, 72-73, 219, 221, 235, 265 (*See* Manual operations)
new knowledge of, from unnatural patterns, 35, 36-37, 54-56, 159, 161-180, 221
optimum level for, 37, 62, 64, 120-121, 188, 193, 264-265
permanent changes in, 62, 72, 228
predictability of, 34, 35, 36, 45-46, 53-54, 64, 71
relation of, to specification, 13-14, 16, 30-31, 34, 35, 48, 48, 53-54, 58-59, 61-65, 66, 71, 119-122, 124, 125, 127, 140, 151, 157, 158, 160-161, 170, 187-189, 195-196, 198-199, 204-206, 219, 220, 223, 224, 226
spread of (*See* Natural spread of a process; Process spread)
stability of (*See* Stability)
where checked, in the shop, 51, 151, 190-192, 207 (*See* Early operations)
(*See* Processes)

Process average
as basis for choosing sampling plans, 244, 245, 250-253, 264, 265
as basis for estimating costs, 245-246, 265
as basis for evaluating product of suppliers, 39
as basis for minimizing inspection, 39, 246, 250, 252, 253, 273-274
as used in Dodge-Romig tables, 250, 253, 254, 255

Process capability
approach to, 36, 47, 63, 64, 71, 73, 74, 83
as used in the shop, 65, 187, 202, 203-204, 217, 221-222
compared with specification, 61-65, 71, 119-122, 124, 125-126, 127, 195
definition of, 34, 35, 36, 45, 47
dependent on a natural pattern, 35, 53, 56, 59-61, 141
evidence of, 36, 63, 71, 149-152, 170-171
importance of, 34-36, 45-47, 53-54, 56, 76, 112
long-term, 61, 64, 196-197

meaning of, 4, 34-36, 45, 56, 61, 71, 74, 75-76, 122, 131, 149-152, 170-171, 234-236, 244, 246, 264-265
numerical estimates of, 45, 56, 58-59, 71, 73, 127, 235
related to OC curve, 244-245, 255, 264-265
related to operational sorting, 120, 121, 235, 265
satisfactory and unsatisfactory, 34-35, 45-47, 61-63, 71, 121, 122
short-term, 61, 64
shown by natural patterns, 53-54, 59-61, 71, 122, 125-127, 170-171
two ways of expressing, 45, 56
use of, in engineering, 34-36, 45-47, 61-65, 119-127, 145, 224-226
use of, in inspection, 234-236, 244, 246, 250, 252, 253, 255, 264-265
wrong estimates of, 60-61, 141

Process capability studies vii, 4, 28, 34-36, 38, 40, 41, 45-74, 75-76, 112, 113, 116, 119-122, 125-127, 187, 195, 199, 219, 220, 223, 228, 235, 265
abnormal data found in, 49, 52-53, 61, 62, 116-117
action based on, 61-63, 67-72, 73, 235, 255, 265
advantages of (*See* Advantages)
amount of data in, 28, 47, 50-51, 61, 62, 63-64, 66-72
analysis of, 47, 51-63, 66-73
as proper basis for sampling inspection, 36, 235, 244, 246, 250, 252, 253, 255, 264-265
as proper basis for shop control charts, 33-34, 36, 38, 40-41, 45, 62, 63-65, 71-72, 187, 193-195, 199
as related to operational sorting, 120, 121, 122, 235, 265
assignable causes in (*See* Assignable causes)
average of long period not a substitute for, 61
characteristics plotted in, 47, 66, 72
collection of data for, 36, 41, 47-51, 55, 62, 63-64, 66, 67, 74, 223, 228
complex patterns in, 54-56, 66, 67-73
complexity of, 36, 45, 47, 63, 72
conclusions from (*See* Conclusions)
control limits for, 51-62, 53
covering entire jobs, 224-225
data for (*See* Collection of data)

decisions in, 47-53, 66, 72
definition of, 3-4, 34, 36, 45-46
description of, 35-36, 47, 75, 76
distribution not a substitute for, 16, 61, 141
economic basis of, 34-36, 45-47, 61-63, 265
effect of skewness on, 56-58, 61, 122
elimination of variables in, 55, 66, 67, 68
end of, 36, 47, 63, 66, 71
examples of, 66-72, 72-73
for cost reduction, 34-36, 41, 46, 62, 64, 71, 223-224, 225-226, 228, 235, 265
for process improvement, 4, 34, 35, 36, 41, 46-47, 62, 63-65, 66-72, 120-121, 235, 265
growing out of shop charts, 40, 199, 223, 228
identification of data for, 49, 51, 52, 53, 54-56, 72-73, 76
ignoring patterns in, 66, 91, 153
importance of, vii, 4, 33-34, 34-36, 38, 40, 41, 45-46, 61-63, 120-121, 125-127, 187, 223, 225-226, 235, 244, 246, 265
importance of *R* chart in, 55, 66, 67, 68 (*See* *R* Chart)
inflated patterns in, 55, 66, 67, 168, 173
instructions for collection of data in, 49, 66, 67, 223, 228
interpretation of, when patterns are in control, 53-54, 56, 61-63, 71-72
interpretation of, when patterns are not in control, 54-56, 59-61, 66-71, 72-73, 189 (*See also* appropriate portions of pages 149-180)
introduction of shop chart before study is completed, 36, 63-64, 71-72, 74, 188, 198-199, 221, 228
knowledge needed in, 38, 40, 54-56, 66, 67, 71, 72, 75, 112, 220
leading to the need for other studies, 34-35, 36, 40-41, 45-47, 63, 83, 223, 228
leading to the need for shop charts 36, 40-41, 45, 62, 63-65, 66-72, 187, 188
length of, 34-35, 47, 63, 66, 72
long and short term estimates from, 61, 64
made by a Quality Control Team, 40, 41, 45, 66, 74, 220, 223, 228
new, as needed, 40-41, 62, 65, 190, 194, 199, 220, 223, 228

- notes recorded in, 49, 51, 53, 66, 67, 70, 71
- number of samples in, 66
- numerical estimates from, 56, 58-59, 71, 72, 122, 127
- objectives of, 34, 45-47, 66, 159, 187, 235
- plans for, 46-51, 66
- plotting of, 51-52, 53, 66-72, 72-73
- point of collection of data for, 49, 51, 151, 187
- preceding a designed experiment, 36, 75, 76, 90, 91, 114
- problems solved by (*See* Problems)
- procedures for (*See* Procedures)
- relation of, to designed experiments, 4, 34, 36, 41, 55-56, 63, 75-76, 77, 83, 90, 91, 112, 114, 120, 121, 218, 220-221, 224
- results from, 61-65, 71-72, 112, 220
- sample size in, 50, 66, 72
- scales for, 51
- selection of samples for, 49, 51, 66, 72
- simplification of patterns in, 54-56, 66-73
- standards and allowances based on, 34, 35, 36, 38, 45-46, 53-54, 56-59, 60-61, 62-65, 119-122, 125-127, 203, 224, 235, 255, 264-265
- study of patterns in, 35-36, 53-56, 59-61, 66-73, 149-180
- substitutes for, 36, 61, 74, 131, 141, 187-188, 228
- terminating with a natural pattern, 53-54, 61-63
- terminating with an unnatural pattern, 54-56, 59-61, 63-64
- theoretical basis of, 34, 35-36, 47, 53-56, 75-76, 149-152
- time covered by, 63, 66, 72
- uninterpretable patterns in (*See* Patterns)
- used as substitute for a designed experiment, 75, 76, 112, 220
- used for determining desired distribution in the shop, 36-37, 63-65, 190, 193-195
- used in design and development, 4, 10, 34-36, 38, 46-47, 52, 54, 60-61, 62-63, 75-77, 114, 119-122, 140-141, 145, 220, 224, 226
- used to decide on economic centerlines, 64, 192, 193-195
- use of shop chart as a continuation of the study, 19-20, 36, 38, 40, 62, 64, 65, 72, 74, 188, 194, 198-199, 203-206, 220, 221, 223, 228, 265
- using attributes data, 48-49, 50, 53, 54, 56, 59, 66, 72-73, 74, 144
- using *c*-charts, 49, 66, 72-73
- using *p*-charts, 19-20, 45, 48-49, 50, 51, 53, 54, 59, 61-63, 73, 74, 194
- using semi-variables data, 49-50, 113
- using variables data, 15-16, 48, 50, 51, 53-54, 56-61, 61-63, 66-72, 119-127
- using work sampling, 50
- using \bar{X} and *R* charts, 48, 50, 51, 53-56, 56-59, 59-61, 61-63, 64-65, 66-72, 83, 119-122, 125-127
- Process checkers
 - appointment of, 192, 201, 223
 - definition of, 213
 - duties of, 198, 205-211, 213-216, 217, 227-229
 - training of, 41, 159, 171, 172, 192, 201, 213, 215-216, 219, 223
- Process control
 - administration of (*See* Administration)
 - breakdown of, 233, 273, 274
 - confidence in, by Inspection, 273-274
 - cost of, 36, 38, 225-226
 - effect of, on choice of sampling plans, 273-274
 - general instruction for, 201, 205-209, 213, 215
 - importance of, 36-38, 62, 64-65, 187, 220, 225-226, 265, 274
 - layouts for (*See* Layouts)
 - objectives of, 36-38, 187, 202
 - planning of, 187-199, 201-209
 - relation of, to inspection, 37, 38-39, 187, 202, 233-236, 244, 246, 262-263, 265, 274
 - responsibility for, vii, 4, 10, 36-38, 39-41, 45, 62, 63-65, 67, 68-70, 77, 83, 101, 120, 121, 125-126, 187-199, 201-229, 233-234, 236, 246, 261, 263, 265, 274
 - restoration of, after trouble, 246, 263, 273, 274
 - savings from, 10, 38, 62, 71, 225-226, 265
 - (*See* Process control charts; Layouts; Quality control teams)
- Process control charts, vii, 4, 36-38, 39-41, 62, 63-65, 74, 125-126, 155, 158, 164, 178, 187-229, 233-234, 235, 265, 268, 274
 - action on (*See* Action)
 - advantages of (*See* Advantages)
 - appearance of, 192, 216
 - as basis for Minimum Inspection plans, 273-274
 - assignable causes on, 25 (footnote), 189, 212-213, 217, 218-219
 - audits of, 38, 41, 198-199, 219, 223, 227, 268, 274
 - based on nature of operation or characteristic, 188
 - based on performance studies, 74, 187-188, 227, 228
 - based on process capability studies, 33-34, 36, 38, 40-41, 45, 62, 63-65, 71-72, 187, 193-195, 199
 - basis for starting, 45, 63-65, 72, 74, 187-188, 223
 - calculations for, 191, 195-197, 201, 208, 209, 210, 213, 214-215, 219, 227
 - centerlines for (*See* Centerlines)
 - changes in (*See* Changes)
 - collection of data for (*See* Collection of data)
 - compared with designed experiments, 38, 77, 187, 219, 220
 - compared with process capability studies, 38, 63, 65, 74, 77, 187, 188, 219, 220, 221
 - continuous checks on, 38, 41, 198-199, 219, 223, 227, 228
 - control limits for (*See* Control limits)
 - cost of, 38, 189, 190-192, 199, 223, 225-226
 - definition of, 36
 - degree of control on, 220-222
 - design of, 63-65, 189-197, 198-199, 211, 219, 223, 227-229
 - difficulty in using, 17, 59, 159, 189-190, 197, 199, 218-219
 - durability of, 192
 - effect of, 37-38, 62, 64, 155, 164, 167, 177, 178, 187, 226, 233, 235, 265
 - effectiveness of (*See* Results)
 - example of, based on process capability study, 63-65
 - experimental uses for, 38, 77, 220
 - holders for, 192, 228
 - importance of, 4, 10, 16, 19, 36, 37-38, 39, 40-41, 45, 62, 63-64, 77, 125-126, 127, 187, 190, 202-206, 217, 218, 220, 223-224, 225-226, 265, 274
 - improvement due to, 37-38, 62, 64, 155, 164, 167, 177, 178, 187, 226, 233, 235, 265
 - information contributed by, 37-38, 64, 71-72, 159, 190, 202, 219, 221
 - installation of (*See* Installation)
 - interpretation of (*See* Interpretation)
 - introduction of, in the shop, 39-41, 62, 63-65, 72, 187-192, 201-216, 223

- Quality control meetings, 39-41, 201-202, 218, 219, 223, 224, 225, 226
- Quality control program
 administration of, vii, 4, 33-41, 187-199, 201-216, 223-229, 234
 development of, vii, 10, 33-34, 41, 224-226
 encouragement of, vii, 33, 34, 41, 223, 225-227, 234, 265, 274
 essential elements of, vii, 4, 33-41, 45-46, 75-77, 187-189, 233-236
 founded on control charts, vii, 4, 33, 34
 installation of, 33-34, 41
 meaning of, 33
 objectives of, vii, 3-4, 10, 33-41, 45-47, 53-54, 61-63, 71-72, 75, 77, 119, 122, 125-126, 169, 187-189, 201-203, 217-226, 233-236, 273-274
 results of, 10, 34-36, 36-38, 46-47, 75-77, 83, 87-89, 100-101, 112, 125-126, 187-189, 201-206, 225-226, 235, 265
 three years old, 225
 training for, vii, 23, 33, 97
- Quality control reports
 (See Progress reports)
- Quality control teams
 cost reduction by, 33, 41, 71, 223-226
 duty to eliminate operational sorting, 122, 235, 236, 265
 duty to evaluate inspection procedures, 223-224, 236
 encouragement of, vii, 33, 40, 41, 224-226, 227
 functions of, vii, 33, 34, 36, 38, 39-41, 64, 66, 75-76, 112-117, 183, 187, 189-190, 191, 192, 197, 198-199, 201-202, 213, 218-219, 220-222, 223-229, 236, 265
 how started, 33
 importance of, vii, 40, 45, 75, 187, 189, 190-192, 198-199, 219, 220, 223-226, 236
 knowledge needed by, 40, 54-56, 66, 67, 71, 75-77, 112, 198-199, 218-219, 220, 223-224
 meetings of, 33, 39-41, 201-202, 218, 219, 223-224, 226, 236
 members of, 33, 36, 39-40, 201-202, 213, 223, 226, 236
 objectives of, 33, 39-41, 45-47, 66, 75, 187, 223-226, 236, 274
 process capability studies made by, 36, 40, 41, 45, 66-72, 74, 220, 223, 228
 reports of, 33, 40, 41, 224, 225-226, 229
- responsible for inspection, 223-224, 236
 responsible for results, vii, 33, 40-41, 190, 201-202, 219, 223, 225-226, 227
 responsible for shop charts, 33, 38, 39-41, 45, 64, 183, 187, 189-192, 193, 197, 198-199, 201-202, 209, 213, 219, 212-222, 223-224, 227, 228-229
 structure of, 33, 39-40, 223, 236
 training of, vii, 23, 33, 97
- Quality control training
 (See Training)
- Quality levels
 enforced by sorting under AOQL sampling plans, 249-251, 252
 required by AOQL sampling plans, 254-255
 required by customer or user of product, 245, 246, 254, 264, 273
 used in inspection, 39, 237-238, 244, 247, 248, 249, 250, 253, 254, 255, 258, 263-265, 273-274
 used in quality rating, 270, 273
- Quality rates
 as source of AOQL's for Final Inspection, 264, 273
 as source of information for inspection planning, 263, 264, 273
 may be affected by too large a Consumer's Risk, 246
- Quality rating, 197, 226, 246, 264, 270, 273
 (See Quality Assurance)
- Quality record of suppliers, 39, 264
- Quality requirements, 254, 264, 270
- Quality standards
 effect of costs on, 244, 246, 255, 265, 273
 expressed as AOQL, 264, 265, 273
 used in inspection, 264-265, 268, 273-274
 used in quality rating, 264, 270, 273
 (See Quality levels)
- Quantity
 as an objective in a quality control program, 10, 33, 36-38, 71, 202, 203, 226
 constant, for a *c*-chart, 20, 191
 of product out of limits, 37, 46, 58-59, 66, 71, 121-122, 160, 189, 204-206, 254
 of product used in sample, 17, 20, 21, 50-51, 66, 113, 191
 (See Output)
- Quarterly summary, of control chart audits, 227
- Quartile range, 198
- Questionable practices, 45, 61, 73
- Question marks (used in marking control charts), 99, 100, 107, 109
- Questions
 asked by operators, 201, 202
 put to machine setters, 202, 217, 218
- Quincunx, 202
- ## R
- \bar{R}
 calculation of, in a designed experiment, 97, 98, 108
 calculation of, in a standard \bar{X} and *R* chart, 12, 14
- Radar system, 4, 20, 21, 191
- Random
 mixture of lines on a control chart, 160, 169
 numbers, 50, 93, 113, 114-116
 patterns, 24, 116, 149, 150, 156, 170
 points on a control chart, 24, 149, 170, 175, 176, 177, 181-182, 274
 variation, compared with residual, 103
 (See Randomness)
- Random fluctuations, 5-7, 9, 24, 46, 103, 149, 156, 161, 173, 175, 176, 203, 237-238
 (See Fluctuations)
- Randomizing measurements in an experiment, 93, 113, 114-116
- Randomness
 in a pattern on a control chart, 5-6, 7, 9, 24, 149, 161, 173, 175, 176
 in control chart theory, 5-7, 24, 149, 150-151, 170
 in process control, 151, 192, 207, 214
 in sampling inspection, 173, 239, 257, 260, 261, 262, 267-268, 270
 (See also Randomizing; Selection of samples; Unbiased samples; Rational sampling groups; Random fluctuations; Random number "Random order" sampling)
- Random samples, 68, 156, 170, 239, 260, 261, 262, 270
 (See Unbiased samples)
- Ranges
 calculation of, 11, 17, 131, 162, 213
 chart for, in a designed experiment, 98, 108, 109
 compared with *r*-square deviation, 170

- notes recorded in, 49, 51, 53, 66, 67, 70, 71
- number of samples in, 66
- numerical estimates from, 56, 58-59, 71, 72, 122, 127
- objectives of, 34, 45-47, 66, 159, 187, 235
- plans for, 46-51, 66
- plotting of, 51-52, 53, 66-72, 72-73
- point of collection of data for, 49, 51, 151, 187
- preceding a designed experiment, 36, 75, 76, 90, 91, 114
- problems solved by (*See* Problems)
- procedures for (*See* Procedures)
- relation of, to designed experiments, 4, 34, 36, 41, 55-56, 63, 75-76, 77, 83, 90, 91, 112, 114, 120, 121, 218, 220-221, 224
- results from, 61-65, 71-72, 112, 220
- sample size in, 50, 66, 72
- scales for, 51
- selection of samples for, 49, 51, 66, 72
- simplification of patterns in, 54-56, 66-73
- standards and allowances based on, 34, 35, 36, 38, 45-46, 53-54, 56-59, 60-61, 62-65, 119-122, 125-127, 203, 224, 235, 255, 264-265
- study of patterns in, 35-36, 53-56, 59-61, 66-73, 149-180
- substitutes for, 36, 61, 74, 131, 141, 187-188, 228
- terminating with a natural pattern, 53-54, 61-63
- terminating with an unnatural pattern, 54-56, 59-61, 63-64
- theoretical basis of, 34, 35-36, 47, 53-56, 75-76, 149-152
- time covered by, 63, 66, 72
- uninterpretable patterns in (*See* Patterns)
- used as substitute for a designed experiment, 75, 76, 112, 220
- used for determining desired distribution in the shop, 36-37, 63-65, 190, 193-195
- used in design and development, 4, 10, 34-36, 38, 46-47, 52, 54, 60-61, 62-63, 75-77, 114, 119-122, 140-141, 145, 220, 224, 226
- used to decide on economic centerlines, 64, 192, 193-195
- use of shop chart as a continuation of the study, 19-20, 36, 38, 40, 62, 64, 65, 72, 74, 188, 194, 198-199, 203-206, 220, 221, 223, 228, 265
- using attributes data, 48-49, 50, 53, 54, 56, 59, 66, 72-73, 74, 144
- using *c*-charts, 49, 66, 72-73
- using *p*-charts, 19-20, 45, 48-49, 50, 51, 53, 54, 59, 61-63, 73, 74, 194
- using semi-variables data, 49-50, 113
- using variables data, 15-16, 48, 50, 51, 53-54, 56-61, 61-63, 66-72, 119-127
- using work sampling, 50
- using \bar{X} and *R* charts, 48, 50, 51, 53-56, 56-59, 59-61, 61-63, 64-65, 66-72, 83, 119-122, 125-127
- Process checkers**
- appointment of, 192, 201, 223
- definition of, 213
- duties of, 198, 205-211, 213-216, 217, 227-229
- training of, 41, 159, 171, 172, 192, 201, 213, 215-216, 219, 223
- Process control**
- administration of (*See* Administration)
- breakdown of, 233, 273, 274
- confidence in, by Inspection, 273-274
- cost of, 36, 38, 225-226
- effect of, on choice of sampling plans, 273-274
- general instruction for, 201, 205-209, 213, 215
- importance of, 36-38, 62, 64-65, 187, 220, 225-226, 265, 274
- layouts for (*See* Layouts)
- objectives of, 36-38, 187, 202
- planning of, 187-199, 201-209
- relation of, to inspection, 37, 38-39, 187, 202, 233-236, 244, 246, 262-263, 265, 274
- responsibility for, vii, 4, 10, 36-38, 39-41, 45, 62, 63-65, 67, 68-70, 77, 83, 101, 120, 121, 125-126, 187-199, 201-229, 233-234, 236, 246, 261, 263, 265, 274
- restoration of, after trouble, 246, 263, 273, 274
- savings from, 10, 38, 62, 71, 225-226, 265
- (*See* Process control charts; Layouts; Quality control teams)
- Process control charts**, vii, 4, 36-38, 39-41, 62, 63-65, 74, 125-126, 155, 158, 164, 178, 187-229, 233-234, 235, 265, 268, 274
- action on (*See* Action)
- advantages of (*See* Advantages)
- appearance of, 192, 216
- as basis for Minimum Inspection plans, 273-274
- assignable causes on, 25 (footnote), 189, 212-213, 217, 218-219
- audits of, 38, 41, 198-199, 219, 223, 227, 268, 274
- based on nature of operation or characteristic, 188
- based on performance studies, 74, 187-188, 227, 228
- based on process capability studies, 33-34, 36, 38, 40-41, 45, 62, 63-65, 71-72, 187, 193-195, 199
- basis for starting, 45, 63-65, 72, 74, 187-188, 223
- calculations for, 191, 195-197, 201, 208, 209, 210, 213, 214-215, 219, 227
- centerlines for (*See* Centerlines)
- changes in (*See* Changes)
- collection of data for (*See* Collection of data)
- compared with designed experiments, 38, 77, 187, 219, 220
- compared with process capability studies, 38, 63, 65, 74, 77, 187, 188, 219, 220, 221
- continuous checks on, 38, 41, 198-199, 219, 223, 227, 228
- control limits for (*See* Control limits)
- cost of, 38, 189, 190-192, 199, 223, 225-226
- definition of, 36
- degree of control on, 220-222
- design of, 63-65, 189-197, 198-199, 211, 219, 223, 227-229
- difficulty in using, 17, 59, 159, 189-190, 197, 199, 218-219
- durability of, 192
- effect of, 37-38, 62, 64, 155, 164, 167, 177, 178, 187, 226, 233, 235, 265
- effectiveness of (*See* Results)
- example of, based on process capability study, 63-65
- experimental uses for, 38, 77, 220
- holders for, 192, 228
- importance of, 4, 10, 16, 19, 36, 37-38, 39, 40-41, 45, 62, 63-64, 77, 125-126, 127, 187, 190, 202-206, 217, 218, 220, 223-224, 225-226, 265, 274
- improvement due to, 37-38, 62, 64, 155, 164, 167, 177, 178, 187, 226, 233, 235, 265
- information contributed by, 37-38, 64, 71-72, 159, 190, 202, 219, 221
- installation of (*See* Installation)
- interpretation of (*See* Interpretation)
- introduction of, in the shop, 39-41, 62, 63-65, 72, 187-192, 201-216, 223

- Process control charts, *continued*
 layouts for (*See* Layouts)
 marking of, 25 (footnote), 192, 194-195, 208-209, 212-213, 215, 217, 218, 221, 227, 229 (*See* Marking *x*'s)
 modification of (*See* Changes)
 mounting of, 192, 228
 need for, 31, 36-38, 62, 63-64, 187-189, 202, 217, 219, 220, 221, 233, 235, 265, 274
 notes on, 206, 208, 209, 212, 213, 215, 217, 218, 221, 227
 not required on certain operations, 190, 224
 number of, 34, 38, 41, 72, 187, 189, 190, 199, 219, 223-225, 226, 227
 objectives of (*See* Objectives)
 philosophy of, 36-38, 187, 201-202
 planning for (*See* Planning)
 plotting of (*See* Plotting)
 points out of control on 212, 213, 221-222, 226, 227
 preservation, 192, 207, 228-229
 problems solved by (*See* Problems)
 records of, 228-229
 removal of, 38, 41, 189, 199, 223, 227
 reports on, 189, 224-225, 225-226
 responsibilities for, 36, 38, 39-41, 45, 62, 63-65, 187, 188, 189-190, 192, 194, 199, 201-202, 203-204, 207-209, 212, 213-216, 217-219, 221, 223-229
 results of, 10, 38, 202, 203-206, 225-226, 233, 235, 265 (*See* Results)
 review of, 38, 41, 189-190, 198-199, 218-219, 223, 227
 revision of (*See* Changes)
 routines associated with, 38, 40-41, 64, 65, 190-192, 205-211, 213-219, 223-224, 227-229
 samples for (*See* Samples)
 saving due to, 10, 36-38, 46, 62, 63, 71, 187, 225-226, 235, 265
 scales for, 13, 17, 65, 190, 199, 214-215, 228, 229
 separation of, for better analysis, 159, 190, 199
 storage of, 192, 207, 228-229
 study of, by Quality control team, 38, 39-41, 74, 198-199, 217-219, 223, 225-226, 228-229
 theoretical basis for, 37-38
 types of, 34, 38, 188-189, 197-198, 225, 227
 usability of, 190, 192, 199, 214-215, 219, 228
 used as substitute for designed experiment, 77, 220
 used as substitute for process capability study, 19-20, 36, 38, 63-64, 71-72, 74, 188, 194, 198-199, 203-206, 218-219, 221, 223, 228, 265
 used for checking trial and error methods, 77
 used for cost reduction, 10, 36, 38, 41, 62, 64, 72, 187-189, 199, 224-226, 265
 use of, by operators, 4, 155, 158, 164, 167, 177, 178, 188, 203, 204, 221, 235, 265
x's on (*See* Marking *x*'s)
 Process control layouts
 (*See* Layouts)
 Process elements (as potential assignable causes), 35, 36, 53, 54-56, 114, 155, 158, 164, 166, 176, 218-219
 Processes
 developed through process capability studies, 34, 46, 47, 76
 existing, 34, 54, 66-72, 72-73, 226
 improvement of (*See* Improvement)
 new, 34, 47, 226
 stability of, 33, 34, 36, 38, 187, 220, 246
 Process information (from control charts), 35, 54, 66-72, 159, 202, 217-219, 220, 221
 Processing
 of material, 158, 218
 time required for, 218, 223
 variables, 4, 47, 48, 54, 114, 218
 Process spread
 affected by a systematic variable, 176
 affected by change in level, 165, 178
 affected by cycles, 162
 affected by instability, 72-73, 166, 179
 affected by interaction, 168
 affected by stratification, 173
 compared with specifications, 13-14, 30-31, 58-59, 62, 71, 119-122, 125-127, 140-141, 151, 195, 205, 224
 estimated from an *R* chart, 53-54, 56, 58, 62, 71, 119, 131, 154-156, 168, 170, 195, 196
 estimated from a process capability study, 53, 56, 58-59, 61, 62, 122, 195
 excessive, 61, 62, 121, 196
 for a non-normal distribution, 56, 59, 61, 122, 134-136, 161, 196
 for a normal distribution, 30-31, 56, 58, 61-62, 122, 131-133, 195
 illustrated by distributions in the shop, 15, 37, 139-141
 in correlation, 144, 145
 long-term, 61, 64, 122
 measures of, 9, 129-131 (*See* Standard deviation)
 of assemblies, 122-127
 reduction of, through process capability studies, 71, 73, 120, 121
 related to spread of sampling distribution, 138
 short-term, 45, 61, 64, 151-152
 studied on a shop chart, 63
 theoretical background for, 151-152, 170-171
 (*See* Process capability; Natural spread of a process)
 Process trouble vs. specification trouble, 122, 204-206
 Process variables
 effect of, 35, 37-38, 54-56, 66-69, 76, 114, 166, 167-169, 212-213, 217-219, 220
 information on, from unnatural patterns, 11, 33, 35-36, 37, 54-56, 66-73, 83, 150-151, 159, 221
 related to cycles, 69-70, 161
 Process variation
 analyzed in a designed experiment, 75-76, 78-80, 81, 82-83, 87-89, 93-101
 analyzed in a process capability study, 35-36, 45-46, 53-56, 58, 59-61, 62, 66-73, 75-76, 83, 120-122, 125-127
 as a form of interaction, 168-169
 explanation of, 5-7, 35, 187-188
 natural, 9, 35-36, 37-38, 45-46, 53-54, 56-59, 59-61, 63, 119-122, 131, 141, 151-152, 156, 170-171
 reflected on a shop control chart, 187-188
 unnatural, 6, 9, 34, 35-36, 37-38, 45, 53, 54-56, 59-61, 141, 150-151
 (*See* Process spread)
 Producer's risk, 244-246, 254-255
 Product
 accumulation of, 167, 246, 260-262
 distribution of (*See* Distributions)
 flow of, 246, 260
 handling of, 38, 156, 163, 246, 260-261, 263, 265
 identification of, 209, 218, 261, 270

- improvement of, 16, 19, 72, 83, 101, 112, 121, 187, 220, 233, 265
 - inspection of, after completion, 264, 270, 273-274
 - junking of, 254, 269
 - knowledge about, 10, 33, 46, 76, 202
 - meeting specification, 61-63, 71, 120, 126, 206
 - normal (See Normal product)
 - of "n" x "p", 191, 240, 241
 - out of limits, 37, 46, 54, 56, 66, 71, 121, 160, 189, 204-206, 254 (See Percentage)
 - rejected by Inspection, 37, 38, 66, 165, 217, 226, 246, 254-255, 260, 261, 262, 263, 265, 273
 - rejected under AOQL sampling plan, 249-251, 252, 254, 255, 257, 263, 265, 273
 - reliability of, 71-72
 - requiring detailing, 46, 120-121, 226, 233-236, 246, 254-255, 256-257, 263, 265
 - return of, to supplier, 254, 261
 - shipped, 246, 264, 270, 273
 - skewness in, 57-58, 69, 70
 - types of, on a control chart, 160
 - undesirable, 217, 262
 - variations in treatment of, 155
 - very good or very bad, 163, 167, 173, 180, 190
 - Product engineers
 - areas of work for, 33, 34-36, 38, 39-41, 66-72, 74, 83, 84-87, 91-117, 119-127, 187-192, 198-199, 212, 213, 220, 221-222, 223-226, 235, 236, 244, 246, 254-255, 260-263, 273-274
 - contributions of, 33, 39-41, 201-202, 223-226, 236, 265
 - responsibilities of, 4, 34-36, 38, 45-46, 61-63, 63-65, 75-77, 112-117, 143-146, 149, 204-205, 209, 227-229, 233-236, 264-265, 270
 - training of, vii, 23, 33, 97
 - Production
 - amount of, 10, 33, 36-38, 71, 202, 203, 217, 224-225 (See Output)
 - as an objective in a quality control program, 10, 33, 36-38, 71, 187, 202, 203, 224-225, 246, 255
 - cycles in, 66
 - data from, 6, 21, 189, 191
 - increases or decreases in, 38, 155, 166, 178, 198, 224
 - interruptions to, 33, 36, 38, 77, 187, 202, 220, 225, 246, 254-255, 263, 265
 - schedules for, 37, 38, 46, 155, 161, 224, 226, 246, 260
 - troubles, 11, 34, 35, 37-38, 46, 48, 66-72, 91, 122, 187-188, 217-219, 220, 224, 226, 273
 - variables (See Shop-type variables)
 - (See Output; Quantity)
 - Production paths, 36, 47, 48, 49, 51, 53, 54-55, 59, 63-64, 66, 68, 72, 75-76, 85, 93, 114, 149, 151, 152, 155, 157, 159, 160, 166-167, 168, 179-180, 187, 188, 190, 199, 202, 207, 212-213, 215, 218-219, 223, 228, 261
 - Productive work, interference with, 33, 38, 77, 202, 246, 260
 - "Product tolerance" specification, 119
 - "Profile" of a distribution, 131 (See Shape)
 - Progress
 - indicators of, 10, 38, 225-226
 - review of, 202, 223, 224, 226
 - watched by operators, 202, 203, 223, 226
 - Progress reports, 33, 40, 41, 224, 225-226, 229 (See Results; Savings)
 - Projection of pin, 123
 - Prominent patterns, 55, 166
 - Promptness
 - in acting on shop charts, 190, 217, 219, 221, 227
 - in plotting shop charts, 214, 227
 - in taking samples, 190, 207, 214, 268
 - Proportions
 - of distributions, 153, 157, 171, 178, 179
 - of effort in a quality control program, 34, 41, 226
 - of scales on charts, 13, 51, 159, 192, 215, 229
 - of \bar{X} and R charts used in shop, 189, 225 (See Percentage)
 - Protection
 - against unsatisfactory quality, 264, 273, 274
 - in emergencies, 233, 246, 263, 273
 - in hands of Inspection, 273, 274
 - of the consumer (See Consumer's risk)
 - of the manufacturer (See Producer's risk)
 - primary and secondary, 233, 265, 273-274
 - under an AOQL sampling plan, 249-251, 252, 255
 - under continuous sampling, 256
 - Psychological
 - habits and tendencies, 116, 260
 - impressions from control charts, 10, 25, 67, 160, 178, 179, 190
 - Psychological advantages
 - of control charts, 9, 61, 101, 190, 202, 203, 224
 - of designed experiments, 77, 101
 - of double or multiple sampling, 260
 - Pumps, 155, 178
 - p Value, calculation of, 162, 215, 229
- ## Q
- Quality
 - adverse effect on, 72, 121, 246
 - assurance of, 270, 274
 - balanced against cost, 33, 193, 264, 265 (See Balance)
 - characteristics, 3, 132, 188, 265
 - charts on, 38, 187, 188, 225, 227
 - controlled by process control charts, 38, 62, 155, 164, 167, 177, 178, 187, 226, 233, 235, 265
 - deterioration of, 246, 273
 - effect of repeated checking on, 246
 - good and poor, in sampling inspection, 237-238, 244-245
 - improvement of (See Improvement)
 - meaning of, 3, 33, 37, 46, 187, 225, 226, 233-234, 254, 264, 273
 - of piece parts etc. (See Piece parts)
 - of shipped product, 246, 264, 270, 273
 - problems, 10, 33, 46, 61-63, 121-122, 187, 189, 202, 224-226, 233-236, 246, 254, 264, 265
 - responsibility for, 216, 233-236, 265, 270, 273-274
 - troubles, 37, 46, 61-63, 66, 72, 187-189, 202, 264
 - Quality Assurance Organization, 197, 226, 263, 264, 270, 273
 - Quality audits, 270
 - Quality control
 - (See Statistical quality control)
 - Quality control coverage, 3-4, 33, 34, 38, 41, 189, 224-225, 226
 - Quality control engineers
 - areas of work for, 33, 34, 39-41, 66-72, 74, 75-117, 187-199, 201-202, 209, 213, 216, 217-219, 220-222, 223-229, 236, 264-265, 273-274
 - contributions of, 33, 39-41, 45, 75-76, 112-117, 202, 216, 220-221, 226, 236
 - responsibilities of, 33, 34-36, 38, 112, 192, 209, 219, 223, 227, 228-229, 236, 270
 - training of, vii, 23, 33, 97

Quality control meetings, 39-41, 201-202, 218, 219, 223, 224, 225, 226

Quality control program
 administration of, vii, 4, 33-41, 187-199, 201-216, 223-229, 234
 development of, vii, 10, 33-34, 41, 224-226
 encouragement of, vii, 33, 34, 41, 223, 225-227, 234, 265, 274
 essential elements of, vii, 4, 33-41, 45-46, 75-77, 187-189, 233-236
 founded on control charts, vii, 4, 33, 34
 installation of, 33-34, 41
 meaning of, 33
 objectives of, vii, 3-4, 10, 33-41, 45-47, 53-54, 61-63, 71-72, 75, 77, 119, 122, 125-126, 169, 187-189, 201-203, 217-226, 233-236, 273-274
 results of, 10, 34-36, 36-38, 46-47, 75-77, 83, 87-89, 100-101, 112, 125-126, 187-189, 201-206, 225-226, 235, 265
 three years old, 225
 training for, vii, 23, 33, 97

Quality control reports
 (See Progress reports)

Quality control teams
 cost reduction by, 33, 41, 71, 223-226
 duty to eliminate operational sorting, 122, 235, 236, 265
 duty to evaluate inspection procedures, 223-224, 236
 encouragement of, vii, 33, 40, 41, 224-226, 227
 functions of, vii, 33, 34, 36, 38, 39-41, 64, 66, 75-76, 112-117, 183, 187, 189-190, 191, 192, 197, 198-199, 201-202, 213, 218-219, 220-222, 223-229, 236, 265
 how started, 33
 importance of, vii, 40, 45, 75, 187, 189, 190-192, 198-199, 219, 220, 223-226, 236
 knowledge needed by, 40, 54-56, 66, 67, 71, 75-77, 112, 198-199, 218-219, 220, 223-224
 meetings of, 33, 39-41, 201-202, 218, 219, 223-224, 226, 236
 members of, 33, 36, 39-40, 201-202, 213, 223, 226, 236
 objectives of, 33, 39-41, 45-47, 66, 75, 187, 223-226, 236, 274
 process capability studies made by, 36, 40, 41, 45, 66-72, 74, 220, 223, 228
 reports of, 33, 40, 41, 224, 225-226, 229

responsible for inspection, 223-224, 236
 responsible for results, vii, 33, 40-41, 190, 201-202, 219, 223, 225-226, 227
 responsible for shop charts, 33, 38, 39-41, 45, 64, 183, 187, 189-192, 193, 197, 198-199, 201-202, 209, 213, 219, 212-222, 223-224, 227, 228-229
 structure of, 33, 39-40, 223, 236
 training of, vii, 23, 33, 97

Quality control training
 (See Training)

Quality levels
 enforced by sorting under AOQL sampling plans, 249-251, 252
 required by AOQL sampling plans, 254-255
 required by customer or user of product, 245, 246, 254, 264, 273
 used in inspection, 39, 237-238, 244, 247, 248, 249, 250, 253, 254, 255, 258, 263-265, 273-274
 used in quality rating, 270, 273

Quality rates
 as source of AOQL's for Final Inspection, 264, 273
 as source of information for inspection planning, 263, 264, 273
 may be affected by too large a Consumer's Risk, 246

Quality rating, 197, 226, 246, 264, 270, 273
 (See Quality Assurance)

Quality record of suppliers, 39, 264

Quality requirements, 254, 264, 270

Quality standards
 effect of costs on, 244, 246, 255, 265, 273
 expressed as AOQL, 264, 265, 273
 used in inspection, 264-265, 268, 273-274
 used in quality rating, 264, 270, 273
 (See Quality levels)

Quantity
 as an objective in a quality control program, 10, 33, 36-38, 71, 202, 203, 226
 constant, for a *c*-chart, 20, 191
 of product out of limits, 37, 46, 58-59, 66, 71, 121-122, 160, 189, 204-206, 254
 of product used in sample, 17, 20, 21, 50-51, 66, 113, 191
 (See Output)

Quarterly summary, of control chart audits, 227

Quartile range, 198

Questionable practices, 45, 61, 73

Question marks (used in marking control charts), 99, 100, 107, 109

Questions
 asked by operators, 201, 202
 put to machine setters, 202, 217, 218

Quincunx, 202

R

\bar{R}
 calculation of, in a designed experiment, 97, 98, 108
 calculation of, in a standard \bar{X} and R chart, 12, 14

Radar system, 4, 20, 21, 191

Random
 mixture of lines on a control chart, 160, 169
 numbers, 50, 93, 113, 114-116
 patterns, 24, 116, 149, 150, 156, 170
 points on a control chart, 24, 149, 170, 175, 176, 177, 181-182, 274
 variation, compared with residual, 103
 (See Randomness)

Random fluctuations, 5-7, 9, 24, 46, 103, 149, 156, 161, 173, 175, 176, 203, 237-238
 (See Fluctuations)

Randomizing measurements in an experiment, 93, 113, 114-116

Randomness
 in a pattern on a control chart, 5-6, 7, 9, 24, 149, 161, 173, 175, 176
 in control chart theory, 5-7, 24, 149, 150-151, 170
 in process control, 151, 192, 207, 214
 in sampling inspection, 173, 239, 257, 260, 261, 262, 267-268, 270
 (See also Randomizing; Selection of samples; Unbiased samples; Rational subgroups; Random fluctuations; Random numbers)

"Random order" sampling plans, 268

Random samples, 68, 156, 170, 179, 239, 260, 261, 262, 267-268
 (See Unbiased samples)

Ranges
 calculation of, 11, 13, 129, 131, 162, 213
 chart for, in a designed experiment, 98, 108, 109
 compared with root-mean-square deviation, 131

- distribution of, 137, 151, 181-183
- equation for, 12, 131
- from a normal population, 156, 181, 182
- of distributions in the shop, 63, 64, 193-197
- tests for, 83, 182-183, 191
- used to estimate σ' , 56, 58, 71, 98, 108, 131
- uses for, 66, 67-68, 131, 154-156, 168, 195
- (See *R Chart*)
- Ranking of measurements, 49-50
- Rapid methods of calculating (See *Shortcuts*)
- Rating
 - of suppliers, 39
 - quality, 197, 226, 263, 264, 270, 273
- Rational sub-groups, 48, 49, 51, 149, 151, 192, 207, 214, 215, 261, 268
- Raw materials, 196, 264
- R chart*
 - as key to interpretation of unnatural patterns, 55, 66-68, 91, 153, 155, 156, 168, 179, 195, 197
 - as key to separation of data by source, 55, 149-151, 154-156, 168-169, 179-180
 - as key to solution of problems, 66, 67, 68
 - bunching of measurements on, 68
 - calculations based on, 56, 58-59, 71, 98, 106, 108, 131, 156, 168, 170, 229
 - causes different from \bar{X} chart, 11, 16, 48, 68, 83, 87-89, 100, 109, 153, 156
 - centerline on, in a designed experiment, 98, 100, 107-108
 - compared with chart for individual measurements, 160, 161
 - compared with residual, 97, 100
 - construction of, 12-13, 82, 85-88, 97-98, 99, 100, 107-109, 111, 229
 - cycles on, 69, 70
 - estimates based on, 54, 56, 58-59, 62, 119, 131, 168, 170, 195
 - examples of, 14, 16, 65, 99, 120-121, 126, 144, 203-206, 212
 - fluctuations on, 67, 69
 - freaks on, 68, 70, 153, 155, 156, 163
 - grouping of measurements on, 68
 - importance of, 11, 15-16, 55-56, 66-69, 89, 91, 125, 127, 144, 153-154, 168, 170, 171, 195, 196, 204
 - importance of, in interpreting complex patterns, 55, 66-68
 - improvement shown by, 71, 155
 - inflation on, 66-67, 168-169
 - instability on, 67, 69, 166-167, 179, 180, 195
 - interaction on, 68, 100, 168-169, 179, 195
 - interpretation of (See *Interpretation*)
 - interpretation of, in a designed experiment, 83, 87-89, 100
 - interpretation of, in an error of measurement study, 87-89
 - isolated points on, 70, 71, 156, 162-164
 - plotting of, in a designed experiment, 82, 85-88, 100, 108-109, 111
 - special tests for, 28, 82, 181-182
 - substitutes for, 197-198
 - variables appearing in, 100, 109, 150, 168
 - x 's on, 67, 68, 168, 195
 - (See *Ranges*)
 - (See also appropriate portions of pages 161-180)
- Readability of patterns, scales etc., 190, 199, 215, 219
- Reading of control charts, 23-25, 36, 66-73, 149-180, 203-206, 217-219
- Re-adjusting, 188 (See *Adjustment*)
- Real effects, changes etc. vs. apparent effects, 9, 10, 46, 56, 61, 67, 75-76, 99, 103, 117, 122, 123, 141, 146, 156, 160, 161, 162, 164, 166-167, 173-174, 176-177, 178, 179, 204, 206
- Realistic specifications, 10, 34, 36, 38, 61-63, 65, 71, 122, 125-127, 140-141, 206
- Re-arrangement of data, 55, 56, 75-76, 85, 109, 117, 143-146, 149, 160
- Re-calculation of control limits, 52, 154, 228
- Re-calibration, 53, 113, 153, 159, 165, 175
- Receiving inspection, 39, 233, 264
- Re-checking, 246 (See *Re-inspection*)
- Reconciliation of results with previous knowledge, 77, 218
- Records
 - for inspection, 268-269, 270, 271
 - for process control, 207-208, 209-210, 228-229
 - kept by statistical clerk, 228-229
 - kept up-to-date, 214-215, 227
 - of accounting, 6, 21, 50, 189, 191, 197, 226
 - of dropouts, 224-225, 227, 264
 - of quality control coverage, 189, 224, 225, 226
 - of quality control meetings, 224, 225, 226
- Rectifier tubes, 224, 225
- Re-design
 - of fixtures, 62, 69
 - of tools, 62, 212, 219
- Reduced data, 106
- Reduced inspection
 - as an inspection level, 120, 246, 247, 262-263, 264, 273-274
 - as cost reduction, 34, 38, 39, 71, 188, 225, 226, 233-236, 246, 273-274
 - through sampling, 39, 233, 234, 236
- Reduction
 - of back schedules, 37, 46, 226
 - of bottlenecks, 33, 187, 202 (See *Delays*)
 - of carelessness, 155, 156, 167, 175, 180, 235
 - of complaints, 38, 62, 226, 246, 264
 - of data, 106 (See *Amount*)
 - of defects, 38, 71, 225, 233, 235, 246, 265
 - of delays, 33, 187, 190, 202, 217, 219, 246, 260, 261, 262
 - of difficulty in meeting schedules, 38, 226
 - of facilities, 38, 246
 - of inspection (See *Inspection*)
 - of losses (See *Losses*)
 - of operators, 38, 226
 - of percent defective, 19, 31, 159, 167, 175, 178-179, 224-225, 233-235, 236, 265
 - of repairs, 4, 10, 33, 46, 188, 189, 225
 - of re-work, 4, 10, 33, 37, 46, 61, 121, 187, 188, 225
 - of scrap, 4, 10, 33, 37, 38, 46, 48, 121, 188, 225
 - of sorting, 46, 122, 226, 235, 236, 275, 263, 265, 273
 - of unnatural variation, 35, 36, 37-38, 66-72, 203, 206
- Reeds, 213
- Reel, 153
- Regression lines, 144-145, 148
- Regular cleaning, 91, 92, 100
- Regularity of progress reports, 33, 224-226
- Regulation of voltage, 10, 48, 162
- Re-inspection of rejected product, 227, 246, 269
- Re-instruction (See *Re-training*)
- Rejected product, sent back to Operating, 37, 226, 246, 261, 269
- Rejection
 - of hypothesis, 47, 82, 83
 - of normal product, 246, 255, 265, 273

- Rejection, *continued***
 of product, in general, 37, 38, 66, 165, 217, 226, 260, 261, 262, 263, 273
 of product under AOQL sampling plan, 249-251, 252, 254, 255, 257, 263, 265, 273
 vs. acceptance, in inspection, 4, 38-39, 188, 233, 237-239, 254, 260-261, 268-269
Rejection number, 248, 259
Related points, in a designed experiment, 109
Relation between process and specification (See Process)
Relationships between variables (See Correlation)
Relaxation
 of inspection, 246, 273
 of requirements, 31, 35, 62-63, 120, 121, 122, 159, 165, 167, 175, 179
 of standards, 165, 167, 179
Relay cores, 64
Relays, 3, 19, 64, 154
Reliability
 of a product, 71
 of averages, 60, 61, 83, 153, 154
 of control charts, 9-10, 25 (foot-note), 52, 149
 of data (See Error)
 of equipment, 46, 180
 of gages, 46, 203, 219, 224, 227
 of holding devices etc., 10, 68, 69, 162, 175, 235
 of information, 46, 61, 75-76, 112, 141, 146
 of measurements, 49, 50, 113, 192, 213, 215-216, 218, 219, 223, 227, 228-229
 of standards, 46, 90-91
 of test sets, 46, 156, 167, 178, 180
 of tests for unnatural patterns, 23, 25, 160, 180-183
Reliance on control charts, 10, 274
Re-location
 of motors, 70,
 of process, 30, 62, 64-65, 120-121, 220
Removal
 of assemblies from chuck, 69
 of charts, 38, 41, 189, 199, 223, 227
 of effects from data, 103, 105, 106
 of inflation, 67-68, 168
 of requirements, 61, 62-63, 165, 175
 of variables in an experiment, 103, 106
Repairs
 as a variable, 10, 15-16, 30, 48, 53, 55, 69, 155, 167, 175, 180, 202, 206
 of assembled units, 64
 of rejected product, 254, 261, 269
 on a fixture, 215
 on a tool, 23
 reduction of, 4, 10, 33, 46, 188, 189, 225
Repeat
 experiments, 77, 112
 measurements, 6, 84-86, 90, 93, 111, 113
Repeatability
 dependent on a natural pattern, 53-54, 60, 61, 150, 170-171
 of measurements (See Precision)
Repeated handling and checking, 246
Repeater tubes, 224, 225
Repetition of pattern, 24, 69, 160, 161, 175, 176
Replacement of gages and test sets, 113
Reports
 intervals between, 33, 225
 of control chart audits, 227
 on process control charts, 189, 224-225, 225-226
 on progress (See Progress reports)
Representative
 periods on shop control charts, 229
 samples, 51, 173, 207, 214, 268, 274
Reproducibility of measurements (See Precision)
Reproductions of shop charts, 65, 192, 207, 228
Requirements
 addition of, 61, 63, 165, 175, 178
 modification of, 10, 61, 62, 122, 153, 198
 quality, 254, 264, 270, 273
 relaxation of, 31, 35, 62-63, 120, 121, 122, 159, 165, 167, 175, 179
 removal of, 61, 63, 165, 175
 tightening of, 31, 165, 175, 178
 trouble in meeting, 15, 19, 66, 121-122, 188, 189, 204, 205, 206, 234, 264
 uneconomical or unnecessary, 10, 34, 35, 36, 38, 48, 62-63, 65, 187, 188
Research
 design of experiment in, 4, 34, 75-77, 112
 method of, 47, 75-76, 112, 220
 problems, 4, 34, 41, 47
 process capability studies in, 34, 35, 45-46, 54-56, 112, 220
Residual (in an experiment), 80, 93, 94-96, 96-97, 98, 100-101, 103, 105, 106, 107, 108, 110, 111
Resistance
 electrical, 12, 119
 insulation, 163
 lamps, 224, 225
 to control charts, 33
Resistors, 4, 119
Responsibilities
 for inspection, 233-234, 235, 236
 for process control, 36, 38, 39-41, 45, 62, 63-65, 187-229
 for quality, 216, 233-236, 265, 270, 273-274
 in control chart audits, 227
 of engineering, 46, 65, 192, 204, 205, 209, 236, 270
 of machine setters, 202-204, 217
 of operators, 203
 of inspectors, 234, 235-236, 267-271
 of statistical clerks, 228-229
 of supervisors, 201-203, 205-209, 213-216, 217-219, 223, 226, 236
 of the shop, 46, 202-206, 233-236 (See Duties)
 (See also Product engineers; Quality control engineers; Quality control teams)
Restoration of process control, 274
Rest periods, 70, 162
Restrictions on data, 106 (See Degrees of freedom)
Results
 consistent, 71, 76-77, 101
 controlled by machine setters, 48, 188, 202, 203-204, 217
 controlled by operators, 46, 48, 188
 of process capability studies, 35-36, 38, 45-47, 53-54, 61-65, 71-72, 112, 220
 of using control charts, 10, 16, 19-20, 33-34, 35-36, 37-38, 46-47, 62, 64, 66-72, 75-77, 83, 87-89, 101, 112, 125-126, 155, 164, 167, 177, 178, 187, 203-206, 219, 221, 222, 224, 225-226, 233, 235, 265, 274
 of sampling inspection, 39, 233, 236, 239, 252, 268-269
 (See Progress reports)
Re-training
 of operators, 46, 73, 155, 180, 204, 219
 of process checkers, 159, 219
 (See Training)
Reversion
 to control chart, after sampling plan, 262, 263
 to sampling plan, after control chart, 246, 262, 263
 to Tight inspection, 273-274
Review
 of layouts, 227
 of process control charts, 38, 41, 189-190, 198-199, 218-219, 223, 227

of progress, 224, 226
 Re-work, 4, 10, 33, 37, 46, 61, 121, 187, 188, 225
 Richardson, W. J., 50, 277
 Rise (in a level or curve), 164, 174
 Risk
 Consumer's, 245, 246
 in an experiment, 97, 100, 107, 109, 112
 of accepting poor product, 245
 of unnecessary rejections, 245-246, 254-255, 265
 of wrong decisions, 25 (footnote), 52, 100, 107, 109, 180-183
 on a control chart, 9, 25, 52
 Producer's 244, 245, 246
 Riveting, 162
 Road conditions, 216
 Rod (of stock), 156, 163
 Rollers, 162
 Romig, H. G., 175, 177
 (See Dodge-Romig)
 Root-mean-square deviation, 131
 Rotation, effect of, 162, 175, 176
 Routines
 associated with inspection, 267-271, 273, 274
 associated with process control charts, 38, 40-41, 64, 65, 190-192, 205-211, 213-216, 217-219, 223-224, 227, 228-229
 interference with, in the shop, 33, 37, 38, 77, 187, 202, 220, 225, 246, 254-255, 261, 263, 265
 R points
 calculation of, 12, 131, 162
 in a designed experiment, 82, 86, 109
 Rubber, 4, 20, 191
 Run-out, 57

S

"s," 130, 197
 Salaries, 22, 146, 203
 Salvage, 226
 "Same essential conditions," 85, 90, 150
 Samples
 alternate pairs of, 108, 109
 check of, 192, 213, 227, 268-269
 complete inspection of, 227, 260, 268
 cost of, in inspection, 260
 for a designed experiment, 82, 84, 85, 98, 107, 108-109, 111, 113, 116
 for inspection, 237-239, 260, 262, 264
 formation of, on a control chart, 4, 85, 108-109, 149, 151
 for process control charts, 190-192, 207, 209, 213, 214, 219, 227

for verification, by Inspection, 268, 274
 in general, 51, 149, 151, 207, 214, 229, 237, 262, 267
 instantaneous, 192, 207, 268
 intervals between, 41, 190-192, 199, 207, 209, 214, 219, 227, 233, 262, 274
 may be the entire lot, 17, 19, 191
 measurement of, 213-216, 227
 number of units in, 12, 17, 18, 19, 20, 50-51, 66, 83, 84, 85, 98, 107, 111, 160, 189, 191
 of chart forms, 211, 229
 of data sheets, 210, 229, 271
 of layouts, 209, 270
 Sample size
 constant, 18, 20, 191, 192
 correctness of, 227
 effect of, on control chart tests, 83, 182, 183
 effect of, on OC curve, 239, 242, 246
 effect of, on R chart, 182, 183, 191
 effect of, on t -chart, 197
 for c -charts, 20, 72-73, 191
 for charts of individual measurements, 11-12, 21, 161, 191
 for np -charts, 20, 191, 209
 for p -charts, 17, 48, 50, 191, 196
 for shop charts in general, 191, 192, 209, 214
 for u -charts, 21, 191
 for \bar{X} and R charts, 12, 13, 31, 50, 66, 83, 84, 85, 98, 99, 107, 138, 144, 191, 195-196, 205, 209
 implications of, when rules are not followed, 51, 192
 in a process capability study, 50-51, 66, 72-73
 in inspection, 39, 226, 239, 242, 246, 265
 in continuous sampling, 256, 257, 258
 in Dodge-Romig tables, 250, 253
 in lot-by-lot sampling, 237-239, 259-260, 261, 270
 in Mil. Std. tables, 247-248
 reduction of, in inspection, 246, 273, 274
 tables for (to obtain control limits), 229
 to be decided by the Quality Control Team, 192
 uneconomical, 191
 variations in, 18, 19, 20, 163, 167, 180, 191
 Samples of 1: 11-12, 21, 161, 191
 Samples of 2: 12, 83, 85, 89, 98, 107-109, 144, 182-183, 191
 Samples of 3: 12, 144, 191

Samples of 4: 12, 144, 182, 191
 Samples of 5: 12, 14, 15, 31, 66, 84, 89, 131, 137-138, 144, 182, 191, 196, 205, 210, 215
 Samples of 10: 12
 Samples of 25: 191
 Samples of 50 and 100: 17, 50, 72, 191
 Sampling
 accuracy of, compared to 100% inspection, 236
 advantages of, in inspection, 39, 236
 as a variable, 29, 167, 171, 172-173, 175, 176, 180, 214
 concepts in, 237-239, 242-245, 249-251, 256, 262, 263, 270, 273-274
 equations in, 239, 251
 fluctuations of, 237-238
 frequency of, 41, 190-192, 199, 207, 209, 214, 219, 227, 233, 262, 274
 from a continuous process, 255-258
 in the shop, 190-192, 199, 205-210, 213-214, 216, 219, 227
 risks of, 237-238, 238-242, 242-245, 246
 tables for, 247-248, 250, 253, 265, 277-278
 theory of, 237-242, 249-251
 verification-type, 268, 274
 vs, 100% inspection, 39, 234, 236
 (See Inspection; Process control)
 (See also Single sampling; Double sampling; Sequential sampling; Multiple sampling)
 Sampling beads, 202
 Sampling distributions, 23-24, 38, 137-138, 180-183
 Sampling fluctuations, 46, 103, 173, 203, 237-238
 Sampling inspection, vii, 4, 38-39, 187, 224, 226, 237-265, 267-271, 273-274
 Sampling intervals
 (See Intervals)
 Sampling plans
 advantages of, 39, 187, 233, 236
 as related to process control, 39, 187, 233-236, 244, 246, 262-263, 265, 273-274
 more than one set of (See Inspection levels)
 operation of, 237-238, 257, 260-261, 262
 reversion to, after control chart, 246, 262, 263
 selection of, 239, 244, 260, 263-265, 273-274
 tentative standards for, 265

- Sampling plans, *continued***
 (See also AQL; LTPD; AOQL; Continuous sampling; Lot-by-lot sampling; Single; Double; Multiple; Chain; Skip-lot; Control chart sampling plans; Variables sampling plans)
- Sampling tables**
 (See Mil. Std; Dodge-Romig)
- Savings**
 apparent, in inspection, 246, 262
 balanced against cost (See Balance)
 calculated, for inspection, 246, 262
 estimates of, 10, 38, 225-226
 example of, 226
 in conducting experiments, 77, 92
 in inspection, 246, 273-274
 in time, 38, 77, 225, 246
 resulting from designed experiments, 62, 83, 101, 120, 121
 resulting from process capability studies, 10, 34-36, 54, 62, 63, 71, 187, 225-226
 resulting from sampling inspection, 39, 187, 233-236
 resulting from shop charts, 10, 36-38, 46, 62, 63, 71, 187, 225-226, 235, 265
 resulting from the use of quality control, 10, 34-36, 36-38, 39, 41, 46-47, 54, 62-63, 119-122, 187, 225-226
 (See Cost reduction; Progress reports)
- Scales**
 exponential, 163
 for charts of individual measurements, 22
 for designed experiments, 83, 87, 88, 99
 for engineering studies, 51, 53, 72-73, 149, 159, 160
 for OC curves, 239, 242, 244
 for *p*-charts, 17, 51, 53, 159
 for shop charts, 13, 17, 65, 190, 199, 214-215, 226, 229
 for \bar{X} and *R* charts, 12, 13, 190
 for \bar{X} chart using various sample sizes, 13
 importance of, 53, 66, 72, 190, 214, 215
 logarithmic, non-linear, etc., 163
 of measurements, 138, 163
 on a *c*-chart, 53, 72, 73
 sub-division of, 55, 72-73, 166
 used for simplifying a complex pattern, 53, 55-56, 72-73, 166-167
- Scatter**
 associated with random variation, 6, 7, 24, 130
 diagrams, 56, 75, 143, 144, 146, 147
- of measurements, 137, 138, 145
 (See Dispersion)
- Schedules**
 back, 37, 46, 226
 changes in, 155, 166, 178, 198, 224
 for maintenance, 46, 155, 162, 164, 180
 for production, 37, 38, 46, 155, 166, 178, 198, 224, 226
 for shipment, 161, 226, 246, 260
 trouble in meeting, 37, 38, 46, 224, 226
- Scientific management**, 33, 34
- Scientific steps in a process capability study**, 35, 47
- Scrap**, 4, 10, 33, 37, 38, 46, 48, 121, 188, 225
- Scratches**, 113
- Screening**
 effect of, on control chart, 49, 52-53, 167, 171, 180, 190
 effect of, on distribution, 57-58, 141
 delays due to, 246, 263
 may lead to loss of information, 49, 52, 190
 (See Sorting)
- Screwdrivers**, 216
- Screw machine**, 6, 8, 9, 10
- Screw threads**, 10, 155, 162, 178
- Seasonal effects**, 161, 162, 178
- Second approximation to the Normal Curve**, 59, 135, 136
- "Second chance," for an inspection lot, 260
- Second order interactions**, 93, 94, 96, 98, 105, 106
- Second shift**, 72, 73, 161, 162
 (See Shifts)
- "Seesaw" pattern, 169
- Segments of a process**, 36, 55, 59, 68, 75, 114, 151, 155, 159, 166, 180, 218-219
 (See Production paths)
- Selection**
 of AOQL standards, 264, 265, 273
 of inspection levels, 273-274
 of representative charts, 229
 of representative periods of data, 74, 228, 229
 of sampling plans, 239, 244, 260, 263-265, 273-274
 of variables for an experiment, 91, 92, 113-114
 of variables to be used for simplifying patterns, 55, 66-68, 72
- Selection of samples**
 by inspector, 237, 239, 257, 259, 260-261, 262, 267-268
 by process checker, 190-192, 207, 209, 213, 214, 219, 227
 for designed experiments, 78, 84, 85, 90-91, 91-93, 111, 113, 116
- for engineering studies, 48-49, 51, 151
 for process control, 151, 190-192, 196, 207, 213, 214, 227
 in order of production, 15, 49, 82, 84, 149, 151, 192, 207, 209, 214
 in rational sub-groups, 48-49, 51, 151, 192, 207, 214, 262, 268
 (See Randomness; Random samples)
- Selective**
 assembly, 124, 127, 188
 system of causes, 156
- Semi-interquartile range**, 198
- Semi-variables measurements**, 50, 113
- Sensitivity**
 of a control chart, 11, 47, 48, 155-156, 157, 158, 160, 161, 165
 of control limits, 52, 161, 173-174
- Separation**
 of data, 55, 166 (See Production paths)
 of distributions, 61, 141, 155
 of shop charts, for analysis, 199
- Sequence**
 of operations, 176, 209, 270
 of points on a control chart, 4, 6, 23-24, 55, 72, 73, 76, 99, 109, 149, 151, 160
 of studies, in determining process capability, 36, 47, 63, 66-72, 74
 tests based on, 25 (footnote)
 (See Order; Arrangement; Control charts in general)
- Sequential sampling**, 259-261
 (See Multiple sampling)
- Series of points on a control chart, etc.**, 4, 6, 149
 (See Sequence)
- Service, weeks of**, 72, 73
- "Settling" of a process, 189, 192, 223
- Set-up**
 of a machine, 174, 188 (See Machine setting)
 of charts, 65, 71, 189-190, 190-192, 219, 227, 228
 parts, 156, 163, 180, 214
- Severity of inspection**, 264, 273
- Shaded boxes or squares**, 97, 106, 107, 110-111
- Shaft**, 126
- Shape**
 changes in, 57-58, 160
 checking on, 16, 30, 53, 56, 59, 138-141, 156, 160-161, 196
 detected by a control chart, 69-70, 156, 176
 estimated from a process capability study, 53, 56, 56-58, 59, 62, 122, 156, 177

- importance of, in a distribution, 56, 59, 61, 122, 125, 126, 131, 138, 153, 154, 158, 160-161, 196
- irregular, 37, 136, 139, 140, 141, 166
- J-shape, 138
- L-shape, 163
- of distribution, 53, 56, 56-58, 59, 61, 63, 122, 129, 131-136, 137, 138, 141, 154, 195, 196
- of OC curve, 242-244, 245
- of the sampling distribution of averages, 138, 180, 181
- of the sampling distribution of ranges, 182, 183
- U-shape, 138
- (See Normal distribution; Bimodal distributions; Multimodal distributions; Symmetrical non-normal distributions; Skewed distributions)
- Sharpening
 - of patterns, 54-56, 67-68, 166-167
 - of tool, 162
- Shavings, 178
- Shewhart, Dr. W. A., vii, 7, 25 (footnote), 288
- Shifts
 - as a time interval, 192
 - as a variable in the process, 36, 48, 54, 72, 73, 162, 171, 175, 176, 207
 - in average, 83, 152-153, 179
 - in distribution, 161, 166, 174
 - in pattern, 11, 30, 53, 55, 56, 72, 82, 111, 152, 156, 161, 164-165, 168, 173, 174-175, 177, 212
 - in process center, 16, 30, 62, 64-65, 120-121, 122, 152, 167, 170, 188, 193-197, 202, 203, 220
 - in spread, 83, 154-155, 179
 - (See Sudden shift; Gradual shift)
- Shimming of doors, 213
- Shipments, 21, 165, 246, 260
- Shipped product, 246, 264, 270, 273, 274
- Shipping schedules, 161
- Shop
 - applications in, vii, 36-38, 45, 62, 63-65, 77, 187-229
 - controls, 36, 62, 273-274 (See Process control)
 - cooperation of, with Engineering, 33, 38, 39-41, 45, 65, 74, 188, 190, 202, 219, 220, 223-226
 - efficiency of (See Efficiency)
 - experience, 40, 54, 77, 91, 101, 201, 202, 219, 236 (See Job knowledge)
 - information for, from unnatural patterns, 35, 37, 54-56, 66-71, 159, 161-180, 217-219, 221, 223
 - people in (See Operators; Machine setters; Operating supervisors)
 - problems (See Operating problems)
 - responsibility, 46, 48, 188, 201, 202, 203, 204, 216, 217, 235
 - results, 10, 38, 224-226 (See Results)
 - routines, 33, 37, 38, 39-41, 62, 63, 65, 77, 187, 202, 220, 225, 245-246, 254-255, 261, 263, 265
 - (See Operating organization)
- Shop charts
 - audit of, 38, 41, 189-190, 199, 219, 223, 227, 268, 274
 - changes due to, 199
 - changes in, 38, 41, 65, 189-190, 198-199, 219, 223, 227-229
 - data for (See Collection of data)
 - extension of, 34, 38, 72, 189, 224-225, 226
 - importance of, 33, 34, 36-38, 41, 62, 63-64, 77, 122, 125-126, 187, 189, 201-202, 217, 219, 226, 233, 235, 265, 273-274
 - improvement reflected in, 74, 199, 228, 229
 - installation of, 63-65, 72, 187-199, 201-216, 234, 265
 - knowledge reflected in, 199, 212-213, 219, 223, 228 (See Notes)
 - maintenance of, 228-229
 - results of (See Results)
 - used as a continuing process capability study, 36, 38, 63-64, 71-72, 74, 188, 194, 198-199, 203-206, 218-219, 221, 223, 228, 265
 - used by operators, 4, 155, 158, 164, 167, 177, 178, 188, 203, 204, 221, 235, 265
 - (See Process control charts)
- Shop coverage, with control charts, 34, 38, 41, 72, 189, 224-225, 226
- Shop supervisors
 - (See Operating supervisors)
- Shop troubles, 4, 10, 11, 15, 19, 34-38, 46, 48, 66, 91, 122, 158, 161-180, 187-190, 202, 203-206, 217, 219, 220, 224, 226, 246, 255, 261, 263, 273
- Shop-type variables, 35, 37, 38, 71, 202, 217, 220
- Short
 - cycles, 160
 - drying, 91, 92, 100, 101
 - production runs (See Intermittent operations)
- Shortage of material, 262
- Shortages
 - (See Back schedules)
- Shortcuts
 - effect of, on skewness, 57, 70
 - in a process, 57, 70, 167, 220
 - in calculation, 97, 98, 110
- Short-term capability, 45, 61, 64, 122, 151-152
- "Shorts," 165, 192, 209, 214
- Shoulder of a curve, 164, 242, 244
- Shrinkage, 48, 226
- (See Scrap)
- Shutdown, effect of, 37
- (See Downtime)
- Sides
 - of parts, 90, 216
 - of squares, 57
- Sigma (σ)
 - as residual in an experiment, 98, 106, 107
 - calculation of, 130-131
 - meaning of, 9 (footnote), 129, 130, 131
 - (See Standard deviation)
- Sigma prime (σ')
 - calculation of, 130, 131
 - estimated from a sample, 131
 - estimated from an R chart, 56, 58, 62, 71, 89, 131
 - in a factorial experiment, 98, 107, 108, 110
 - inflation in, 131
 - meaning of, 9 (footnote), 131
 - (See Sigma)
- Sigma zones, 25, 27, 182, 183
- Signals, electrical (obscured by noise), 68
- Significance
 - levels (1%, 5% etc.), 97, 99, 100, 107, 108, 109
 - of correlation coefficient, 146
 - of results in a designed experiment, 79, 80, 81, 83, 89, 96-97, 100, 103, 107, 109, 112, 117
 - on a control chart, 25-30, 52, 149-183
 - tests of, 25 (footnote), 78-81, 96-97, 99-100, 107, 109, 180-183
- Significant
 - as one of the concepts associated with assignable causes, 6, 24-25, 35, 46, 75, 112, 149, 150, 171
 - categories of data, 36, 55, 59, 75-76, 92, 114, 157, 159, 166, 218-219, 261
 - differences, 6, 16, 25-28, 35, 36, 46, 61, 75, 78, 79-81, 82, 87-88, 96-97, 99, 103, 107, 109, 112, 145, 146, 150, 218-219

- Significant, *continued*
 patterns, 35, 55, 166 (*See* Pat-
 terns)
 points in an experiment, 99, 109
 relationship between variables,
 35, 56, 176-177 (*See* Cor-
 relation)
- Signs disregarded, 21, 98, 107
- Simon, L. E., 278
- Simple
 experiments, 75, 76-77, 77-91, 91-
 117
 interpretation of control charts,
 30-31
 numbers, for process checking,
 215
 relationships between parent and
 sampling distribution, 138
 relationships between process and
 specification, 120-121, 204-
 206
 shift in level, 11, 54, 55, 56, 72,
 152, 156, 164-165, 173, 174-
 175, 177
- Simple causes
 for complex patterns, 6, 37-38, 54,
 66-69, 70, 166-167
 on a shop chart, 71, 72-73, 190,
 203-206, 212-213, 215, 217
- Simple shifts and trends, 54, 55, 56,
 72
- Simple unnatural patterns, 54, 56
 (*See* Unnatural patterns)
- Simplicity
 in administering inspection, 260
 in analysis, 32, 91, 97
 of tracing cycles, 69, 162
- Simplification
 of a *c*-chart, 72-73
 of an \bar{X} and *R* chart, 54-56, 66-72
 of a *p*-chart, 48, 59, 73, 157, 159,
 190, 218
 of complex patterns, 11, 36, 53,
 54-56, 66-70, 72-73, 75, 106,
 166, 218-219
 of data in an experiment, 102-103,
 105, 106
 of shop charts, 19, 38, 41, 63,
 70-71, 72-73, 189-190, 192,
 197, 199, 219, 221-222, 223,
 228-229
 of the use of control charts, 51, 151
 of unnatural patterns (*See* Un-
 natural patterns)
 of variables in an experiment, 106
- Singleness
 of causes, 3, 45, 59, 68, 70, 154,
 157
 of distributions, 45, 150, 170, 171
 of elements in a cause system, 55,
 68, 114, 166, 218-219
 (*See* Production paths)
- Single sampling, 237-238, 240, 242,
 247-248, 250, 253, 259-260
- Six months report, 225
- Size
 of inspection areas, 260
 of lots (*See* Lot size)
 of samples (*See* Sample size)
- Skewed distributions
 data required to estimate shape of,
 30, 53, 56, 59, 141, 196
 description of, 131, 134, 156
 equation for (Second Approx-
 imation), 135
 examples of, 57, 58, 59, 163
 percentage outside of limits in,
 59, 135-136
 spread of, 56, 59, 61, 62, 122, 196
 tables for, 135, 136
 types of, 57-58, 134-136, 138, 156
 (*See* Non-normal distributions)
- Skewness
 allowance for, 56, 61, 122, 154,
 161, 196
 caused by freaks, 58, 153, 162-163,
 166-167
 caused by mixture, 57-58, 179
 caused by screening, 57-58, 141,
 154
 causes of, in general, 57-58, 69-70,
 141, 153, 154, 162-163, 166-
 167
 degrees of, 131
 effect of shortcuts on, 57, 70
 estimates of, 53, 56, 61, 122, 196
 indications of, on a control chart,
 16, 70, 156, 177
 measure of, 134
 permanent or non-permanent,
 56-58
 positive or negative, 134, 135,
 136, 156
 stable or unstable, 56-58
 types of, 131
 (*See* Skewed distributions)
- Skill, 30-31, 38, 55, 72-73, 155,
 158, 164, 167, 168, 170, 175,
 178, 180, 202, 203, 204, 235
- Skip-lot sampling plans, 39, 262,
 278
- Sliding portions (of a head on a
 machine), 71
- Slivers, 270
- Slope
 of a distribution, 159
 of a curve, 164
- Small, Bonnie B., 101, 278
- "Small runner" tubes, 224, 225
- Snedecor, G. W., 101, 278
- Sockets, 155
- Soldering operations, 17, 20, 64,
 215, 219
- Solutions, chemical, 23, 152, 178, 218
- Solutions of problems, 10, 34, 36, 38,
 45-46, 67, 75, 112, 121, 187,
 220
- Sorting
 by Inspection, 188, 226, 234, 249-
 251, 254
- by Operating, 46, 71-72, 120-122,
 190, 191, 226, 235, 246, 252,
 254-255, 260, 261, 263, 265,
 273
 corrective, 234-235
 effect of, on product, 49, 52, 57-
 58, 71-72, 162, 167, 171, 180,
 190, 234
 may cause temporary skewness,
 57-58, 141, 156
 need for, 120, 121, 122, 235, 265
 normal amount of, of, 46, 120-121,
 226, 233-236, 246, 254-255,
 256, 257, 263, 265
 not always required in process
 control, 263
 of product associated with out-of-
 control points, 263
 of rejected product, 39, 234-235,
 246, 249-251, 252, 254, 255,
 261, 263, 265
 one hundred percent, 46, 71-72,
 120, 121, 122, 190, 191, 226,
 235, 265 (*See* Sorting of re-
 jected product)
 operational, 120, 121, 122, 233,
 234-236, 265
 reduction of, 46, 122, 226, 235,
 236, 255, 263, 265, 273
 required by control chart sam-
 pling plan, 263
 required by use of AOQL sam-
 pling plans, 249-251, 252,
 254-255, 256, 257
 (*See* Detail inspection)
- Sources
 of complexity (*See* Production
 paths)
 of data, in a process capability
 study, 47, 48, 49, 51, 53, 55,
 63-64, 66, 68, 72, 75-76, 152,
 154-156, 160, 228
 of information (*See* Unnatural
 patterns)
 of product, 171, 261 (*See* Ident-
 ification)
 of samples, 48, 49, 51, 66, 68, 151,
 157, 163, 167, 172, 173, 176,
 214 (*See* Selection of samples)
 of trouble, 46, 51, 187-188, 190,
 202-206, 217-219, 220 (*See*
 Early operations)
 of variation, in a designed ex-
 periment, 78, 84, 85, 89, 90,
 93, 94-97, 98, 102-103, 104-
 106, 111, 112, 117
 of variation, in a shop process,
 35, 37, 62, 63-64, 158, 159,
 187-188, 190, 202, 212-213,
 215, 217-219, 220, 223
 of voltage supply, 48
 separation of data according to
 (*See* Production paths)
- Space required for storage, 228-229,
 246, 260

- Spacing (as a variable), 177
- Special cleaning, 91, 92, 100, 101
- Specialists
to assist in planning experiments, 112-113, 114
to assist Quality Control Teams, 40, 219, 236
- Special lots, 76, 77, 92, 101
- Special tests
for p -chart, 28, 183, 191
for R chart, 83, 182-183, 191
for \bar{X} chart, 109, 182
- Specification limits
centering process between, 64, 65, 120-121, 160, 193, 220
check on, 10, 34, 35, 36, 38, 48, 62-63, 64-65, 122, 187, 188, 204-205, 206
compared with process, 54, 58-59, 119-122, 140 (See Process)
confused with control limits, 16, 30-31, 151, 190
difficulty in meeting, 15-16, 19, 61, 64, 66, 71, 121, 122, 187, 189, 204-206, 224
for assemblies, 122-127
how marked on control charts, 13-14, 16, 30-31, 65, 190, 205, 206, 212
not compatible with each other, 64, 121
product outside of, 30-31, 37, 46, 54, 56, 58-59, 61, 64, 66, 71, 120-121, 127, 132-136, 160, 189, 204-206, 225, 234-235, 254
used for classifying units of product, 157
(See Specifications)
- Specifications
action on, in a process capability study, 61-63, 64-65, 120, 121, 122
added or removed, 61, 62, 63, 165, 175, 178
affected by correlation, 64, 121
as basis for "modified" limits on shop chart, 64, 195-196
based on process capability study, 34, 35, 36, 46, 48, 56-57, 119-120, 121, 122
changes in (See Changes)
checked by process capability studies, 34, 35, 36, 46, 48, 61-63, 64-65, 119-122
checked by process control charts, 187, 188, 204, 205
compared with chart for individuals, 160, 161
compared with collection of units, 140
compared with control limits, 13-14, 16, 30-31, 151, 190
compared with process (See Process)
comparisons with, to be based on natural patterns, 53-54, 58, 59, 61, 122, 170, 204-206
conflicts with, 10, 31, 33, 34, 36, 38, 61-63, 64-65, 120, 121, 122, 187-189, 204-206, 219, 224, 226
difficulty in meeting, 15-16, 19, 61, 64, 66, 71, 121, 122, 187, 189, 204-206, 224
distributions compared with, 119-122, 140
during design and development, 35, 36, 45-47, 54, 60-63, 75-76, 83, 91, 101, 122-123, 124-127, 141, 198-199, 220, 224
economics of, 34, 35, 36, 61-63, 64-65, 71, 119-122
effect of assignable causes on, 53, 61, 122, 195, 204, 206
expressed in terms of distributions, 119
importance of, 36, 62-63, 65, 119, 122, 187, 188, 224
improvement in, 10, 35, 36, 38, 46, 48, 61-63, 65, 122, 125, 188, 219, 224, 226
indicated on a shop chart, 13-14, 16, 30-31, 65, 190, 205, 206, 212
manufacturing problems associated with, 10, 34, 35, 61-63, 64-65, 119-122, 204-206
maximum and minimum, 119, 202 (See Maximum)
modified as result of process information, 61, 63, 65, 122, 198, 219
nominal value in (See Nominal)
not compatible with each other, 64, 121
problems in establishing, 34-36, 46, 56-57, 119-127
product outside of (See Out of limits)
"product tolerance" type, 119
removal of, 61, 62, 63, 165, 175
re-worded or clarified, 61, 63
shifted to another place, 63 (See Nominal)
study of, 46, 48, 122, 188
suitability of, 34, 35, 71, 187
types of, 119, 124, 126, 202
widened or narrowed, 61, 62 (See Limits; Tolerances; Requirements; Standards)
- Specification trouble, 62, 122, 203-206
- Specified procedures, 39, 190, 192, 205-211, 213, 214-216, 217, 227, 236, 267-271
- Spindle, 151, 173
- Splashes of metal, 209
- Spoiled work, 189, 214 (See Dropouts)
- Spoolheads, 5, 7, 9, 10, 11, 64
- Spot checks, 190, 201, 218, 224 (See Casual checking)
- Spraying operation, 165
- Springs (on a relay), 19, 53, 270
- Spread
change in, 71, 120, 121, 154-156, 179
estimated from a process capability study, 56, 58, 61, 62, 71, 119-120, 124, 125, 127, 131
expected, 162, 165, 176, 177-178
of a distribution, 30-31, 53, 56, 58, 62, 63, 71, 121, 122, 123, 129, 130-131, 138, 140, 158, 160, 166, 195, 196, 204
of distribution (as an inspection requirement), 119, 122, 265
of individual measurements, 16, 30-31, 53, 56, 58, 62, 88, 89, 122, 131, 137-138, 151-152, 160, 170, 195, 196
of process (See Process spread)
of the sampling distribution of averages, 16, 30-31, 137, 138
reduction of, 37-38, 66-71, 121 (See Dispersion; Ranges; Standard deviation; Variance; Natural spread)
- Square root values
in a designed experiment, 98, 110
used by statistical clerks, 229
- "Square root of n " relationship
between scales on a control chart, 13, 161
between parent distribution and sampling distribution of averages, 16, 30-31, 137, 138
used in test for two related points, 109
- "Square root of the sum of the squares," 89, 110, 123-124, 125, 127
- Squares
areas of, 57
in an experimental design (See Boxes)
sides of, 57
sums of (See Sums of squares) (See also Square root)
- Squaring, as a cause of skewness, 57
- Stability
of a production process, 10, 33, 34, 35, 36, 37-38, 64, 67, 69, 71, 166, 170-171, 187, 194, 218, 226, 246
of measurements (See Precision)
of testing equipment, 156, 157, 178, 180, 218
on a control chart, 24, 67, 68, 149, 150, 157, 170-171, 171-174 (See Balance)

- Stability, *continued*
 statistical, 6-7, 9, 24-25, 53, 149-151, 166, 170, 171
 tests for, 9, 23, 25 (footnote), 25-28, 53, 180-183, 208-209, 215, 218
 (See Constant system of causes; Natural pattern on a control chart; Statistical control)
- Stable forms of mixture, 11, 29, 53, 54, 150, 161, 170, 171, 172-174, 175-176
 (See Mixtures)
- Stacking of material, 114
- Stages of growth (in a quality control program), 33, 41
- Standard control chart tests, 23, 25-28, 182, 183
- Standard control limits, 7-8, 12, 13, 17, 18-19, 20, 21, 22, 53, 83, 98, 108, 194-195, 196, 197, 229
- Standard costs, 46, 54
- Standard deviation
 addition of, 89, 123, 124-125, 127
 calculation of, 130-131
 meaning of, 9 (footnote), 130, 131
 obtained from R chart, 56, 58, 62, 71, 89, 131
 of a distribution, 56, 58, 129, 130-131, 138, 139-140
 of a process, 56, 58, 131, 195-196
 of a sample, 130, 197
 of a universe, 131, 138
 of the sampling distribution of averages, 138
 proportional to magnitude, 177
 (See Process spread; Sigma)
- Standards
 adopted by customer, 245, 264, 270
 AOQL, 264, 265, 273
 changes in, 31, 158, 159, 165, 175, 178, 268
 comparison with, 49, 54, 90, 91
 establishment of, 34, 35, 36, 38, 46, 54, 61, 119, 122, 187, 188, 219, 221-222, 235, 264, 265, 270, 273
 expressed in the form of specifications, 34, 62-63, 119, 122, 160
 fixed, 49, 90-91
 for inspection, 264, 270, 273
 for wage incentives, 34, 46, 50, 203, 224, 226, 235
 of frequency, length, width etc., 90
 of quality (See Quality standards)
 relaxation of, 165, 167, 179
 reliability of, 46, 90-91 (See Test equipment)
 severity of, 273
 tentative, 62, 64, 265
 tightening of, 61, 62, 165, 194, 264, 273-274
 to be based on a natural pattern, 35, 53-54, 56, 58, 59-61, 122, 204-206
 used by inspectors, 268
 used for p -charts, 157-159
 used in quality rating, 264, 270
- Standard values
 for a control chart, 120
 for measurement, 90-91
- State of control
 (See Control)
- Statistical
 analysis, 7-9, 10, 36, 66-72, 72-73, 78-84, 84-91, 91-101, 190-192, 219.
 (See Statistical methods; Control charts)
 balance, 59, 76, 93, 150, 157, 159, 170-171 (See Stability; Statistical control)
 correctness of charts, 190
 design of experiment, 4 (See Design of experiment; Designed experiments)
 evidence, 103, 109, 111-112, 218
 fluctuations, 5-9, 46, 173, 203
 instability (See Instability)
 knowledge, importance of, 9, 40, 45-47, 77, 113, 218
 laws, 6-7, 9, 24-25, 123-124, 137-138, 214, 239
 limits, 6-7, 16, 97, 99, 100, 107, 109, 122, 138, 151-152 (See Control limits)
 methods, 78-81, 83-84, 91, 93, 93-97, 101, 129-141, 143-148 (See Control charts)
 patterns, used in inspection, 39, 263, 274
 quality control (See Statistical quality control; also various headings under "Quality control")
 rules for sampling, 207, 214, 239, 267-268
 sampling (See Sampling plans; Shop charts)
 sampling plans (See Sampling plans)
 stability (See Stability; Natural pattern)
- Statistical addition of tolerances, 122-127
 (See also Overlapping tolerances; Assembly tolerances)
- Statistical clerks, 216, 228, 229
- Statistical control
 concept of, 5-7, 9-10, 23-25, 37-38, 149-151, 170-171
 importance of, 10, 35-36, 38, 45-46, 53-54, 122, 217, 219, 221
 meaning of, 3, 9, 24, 150, 170-171
 theory of, 149-151, 170-171
 (See Control; State of control)
- Statistical phenomena
 in laws relating distribution and fluctuation, 6-7
 seen as distributions, 6-7
 seen as fluctuations, 5-7, 24-25, 46, 149-151, 170-171, 237-238
- Statistical procedures
 in designed experiments, 77-117
 in process capability studies, 36, 45-74
 in process control charts, 38, 187-199, 217-219
- Statistical quality control
 books on, 277-278
 meaning of, 3, 4
 results of, 10, 36, 38, 225-226
 suitable areas for, 33-34, 66
 (See Quality control)
- Statistical Research Group, Columbia University, 278
- Statistical sampling inspection, vii, 4, 38-39, 237-265, 267-271
 advantages of, 187, 233-236
 by variables, 262
 compatible with emphasis on process control, 39, 187, 224, 227, 233-236, 244, 245-246, 265, 273-274
 economy of, 39, 226, 236, 239, 244, 265, 273-274
 explanation of, 38-39, 237-239
 information furnished by, 268-269, 271
 not to be substituted for control by Operating, 39, 216, 233-234, 265, 274
 precautions in dealing with, 39, 245-246, 254-255
 using control charts, 262-263, 273-274
 (See Inspection; Sampling inspection; Sampling plans)
- Statistics
 as background of control charts, 5-7, 9, 24-25, 82, 83, 131, 137-138, 149, 151
 as background of sampling inspection, 237-238, 238-242
 based on the Law of Large Numbers, 6-7
 books on, 277-278
 plotted on control charts, 23, 137, 138, 151, 197, 198
- Stevens, W. L., 262, 278
- Stock (of material), 152, 153, 156, 246, 260
- Stop (on a machine), 57
- Storage
 of product, 246, 260
 of shop charts, 192, 207, 228-229
 Storeroom, 164, 167, 171, 254
 (See Storage)
- Straightedge, used to check plotting, 215

- Stratification, 11, 28, 29, 53, 54, 57, 83, 111, 150, 155, 157, 161, 165, 170, 172-174
- Strength
of solution, 152
of welds, 12, 57
- Striking out
of duplicates, 112
of identification, 108
- Strip (of stock), 156, 163
- Studies of a process
(See Process capability studies; Engineering studies)
- Subassemblies, 4, 167
- Subcomponents, 4, 55
- Subdivision
of data, 36, 55, 72, 75, 166, 218
of scale on a *c*-chart, 72
- Subgroups, rational, see rational subgroups
- Subsequent operations, 164, 189, 264
- Substitute jig, 212
- Substitutes
for control charts, 41
for designed experiments, 76-77, 91-92
for process control, 39
for standard forms of control chart, 197-198
- Subtraction, error in, 162, 163
- Success of control charts, 202, 213, 214, 215
- Success of experiments, 10, 38, 75, 77, 101, 112, 220
- Successive
pairs of samples, 108, 109
ranges (See Moving range)
- Sudden
breakdown in process controls, 273
change in level, 53, 54, 55, 56, 111, 152, 161, 174-175
- Suitability
of an instrument, 85, 88
of areas for applying statistical quality control, 66
of a specification, 34, 35, 48, 187
of control chart tests, 28, 182, 183
of inspection levels, 264, 273-274
of inspection plans, 236, 246, 254-255, 264-265, 273-274
of measurements, 49, 113
of process controls, 61-65, 187, 189-190, 227, 233
- Summary
condensed, 229
control charts, 221-222
in form of "*u*" chart, 197
of a job, 48, 188, 229
of conclusions, in an experiment, 100-101, 111-112
of cost reduction cases, 226
of open items in control chart audits, 227
of results, 224-226
of tests for unnatural patterns, 27, 183, 208
"Sum and range" charts, 197
Summing across a variable, 99, 106, 107, 109
- Sums of squares
compared with control charts, 97, 98, 101, 106
in analysis of variance, 80-81, 93-97
in correlation, 145
in error of measurement, 89
- Supervision, 164, 169, 178
- Supervisors
(See Operating supervisors; Inspection supervisors)
- Suppliers
as a variable, 4, 36, 55, 153, 162, 207
contacts with, 40, 219, 223, 224
material returned to, 254, 261
of assemblies, 4, 260
of parts, 174, 207, 260
quality record of, 39
- Surface conditions, 168, 219
- Surveys, 34, 227, 270
(See Audits)
- Switchboards, 3
- Switches, 3, 66-72, 206, 209
- Symbols
for attributes control charts, 17, 20, 21
for boxes in a designed experiment, 98, 99, 109
for *c*-charts, 21
for inspection plans, 238, 240, 246, 249, 251, 256, 259
for moving range control charts, 21
for *np*-charts, 20
for *p*-charts, 17
for *u*-charts, 21
for \bar{X} and R charts, 12
translated into original data, 45, 100, 108
used in plotting experiments, 108, 109
- Symmetrical non-normal distributions, 134
(See Non-normal distributions)
- Symmetry, 28, 57, 131, 183, 191
- System
lack of, in a natural pattern, 24, 161, 175 (See Random fluctuations)
for applying quality control, 33-34
- Systematic variation (or systematic variable), 11, 29, 53, 54, 150, 161, 161-162, 175-176
- Systems of causes
constancy of, 6-7, 9, 83, 150, 170-171
definition of, 3-4, 34-36, 45, 150-151, 170, 171
difference in, 52
selective, 156

T

- "*t*"
calculation of, in estimating percentage, 58, 59, 127, 133, 134, 135, 136
calculation of, in testing correlation coefficient, 146, 147
calculation of, in *t*-test, 80
meaning of, 197
use of, in quality rating, 197
(See *t*-Test)
- Tables for statistical clerks, 229
- Tables of sampling plans, 247-248, 250, 253, 258
- Tail
of distribution (See Shape; Percentage out of limits)
of OC curve, 244
- Talks to operators, 201-202, 223, 226 (See Meetings)
- Tank, 152
- Taper, 90, 223, 226
- Target value in a sampling plan, 254-255
- t*-Chart, 197
- Teachers, 146
- Teams
(See Quality control teams)
- Technical knowledge, 40, 54, 75, 114, 177, 218, 219, 223-224
- Technical terms
for attributes charts, 17, 20, 21
for variables charts, 12, 21, 198
general, 3, 6, 11, 12, 29, 34, 45-46, 50, 61, 74, 129-131, 137, 139, 144-146, 149-152, 167
related to experiments, 76, 87, 90, 101, 103, 104, 106-107, 167
related to inspection, 233-235, 238, 244, 245, 247, 249, 251, 256, 259, 267, 273-274
related to process control, 36, 194, 195, 205-207, 229
(See Definitions; Symbols)
- Techniques
for classification of data, 54-56, 166
of operators, 30, 204 (See Work habits)
used in quality control, 4, 33-41, 78-84, 93-97, 97-101, 110-111, 143-148, 278

- Temperature, 6, 11, 21, 47, 102, 104, 114, 117, 152, 162, 164, 167, 178, 189
- Temporary skewness, 56-58
(See Skewness)
- Tendency to follow (said of a control chart), 11, 16, 29, 53, 54, 70, 84, 153, 156, 161, 176-177, 219, 223
(See Correlation)
- Tentative standards, 62, 64, 265
- Terms
(See Technical terms)
- Test equipment, 3, 38, 46, 47, 113, 156, 159, 174, 175, 178, 180, 218, 246
- Testing
as a form of measurement, 218
as a process variable, 46, 53, 113, 152, 153, 154, 155, 158, 159, 162, 165, 166, 167, 168, 171, 174, 175, 178, 180, 215, 218
(See Error of measurement)
destructive, 188, 197
statistical (See Tests)
- Tests (statistical)
based on runs, 23-30, 180-183
based on zones, 23-30
control chart, 23-30, 99, 100, 107, 109, 180-183
for constancy, 25-28, 78
for normality, 78-79, 133-134
(See Tests for unnatural patterns)
- Test sets
as a process variable, 10, 47, 49, 53, 113, 154, 167, 171, 174, 175, 218, 219, 224, 227
calibration of, 153, 159, 165
drift in, 90, 178
inspection of, 227
maintenance of (See Maintenance)
needed for productive work, 246
used as a standard, 91
(See Test equipment)
- Tests for unnatural patterns, 9, 23-30, 83, 100, 107, 109, 180-183, 208-209, 213, 215
background of, 25 (footnote), 180-183
calculation of, 25, 28, 180-183
description of, 23-25
directions for, 25-30
for ranges of samples of 2: 83, 182-183
for unsymmetrical control charts, 28, 182-183, 191
importance of, 23, 25, 53, 83, 100, 192, 213, 215, 217, 218, 227
one-sided, 25-28, 182
probabilities used in, 180-183
summary of, 27, 183
- theoretical basis for, 23-25, 180-183
two-sided, 28, 182
used in designed experiments, 99, 100, 107, 109
used in inspection, 262-263
used in process capability studies, 53, 66-73
used in the shop, 203-206, 208-209, 212-213, 215, 217-219, 227
- Tests for significance
(See Significance)
- Theoretical curve fitted to data, 139-141
- Theory
of control charts, 5-7, 7-9, 23-25, 34-38, 53-56, 66-71, 149-180, 180-183
of control limits, 7-9, 16, 23-25, 132, 138, 149, 151-152
of designed experiments, 75-77, 83-84, 84-85, 101-106
of distributions, 6-7, 23-24, 123-124, 129-138
of process capability studies, 35-36, 45-47, 53-56, 61, 75-76, 112
of sampling inspection, 38-39, 237-245
of shop charts, 36-38
- Thickness
of plating, 92, 93, 101
of stock, 152
- Third order interaction, 105, 106
- Threads
(See Screw threads)
- Three factor experiment, 89, 90, 110
- Three sigma control limits
as basis of tests for unnatural patterns, 25 (footnote), 180
(See Tests for unnatural patterns)
as test of significance, 25 (footnote), 78-81, 96-97, 107, 180, 278
compared with other control limits, 100, 107, 109
in an experiment, 99, 100, 107-108
on a control chart, 9, 25 (footnote), 25-27, 56, 61, 71, 99, 100, 107-109, 122, 132, 138, 151, 181, 182, 195, 196
(See Control limits)
- Three year old program, 225
- Tightening of standards, 165, 175, 178
- Tight inspection
as an inspection level, 233, 246, 247, 264, 273, 274
in Mil. Std. tables, 247-248
used as a basis for other inspection levels, 273-274
- (See also Emergencies)
- Tightness
of AOQL sampling plans, 251, 252, 273-274
of assemblies, etc., 70, 126-127
of limits, 61-63, 188, 202, 204-206 (See Tolerances; Specifications)
of quality requirements, 264, 273
- Time
allowed for cooling, 69
as a basis for arranging points in sequence, 149, 151, 160
as a basis for rational subgrouping of data, 76, 149, 151, 192, 207, 214
as a variable, 76, 78, 84, 149-151, 152, 153, 162, 166, 168, 178
as related to causes, 56, 69, 162
available for making product, 71, 203 (See Efficiency)
covered by a process capability study, 50, 66, 76
engineering, 63-64, 77, 92, 246
of check, 190, 192, 207, 214
(See Checking intervals)
of day, 49, 114, 162
required for determining process capability, 63, 72
savings in, due to process control charts, 38, 71, 203, 225
spent on repairs, 38, 225, 226
to identify causes, 217, 219
to select samples, 49, 51, 190, 192, 207, 214
used as a means of tracing cycles, 69, 162
waste of, 66, 77, 92, 225, 246, 262
(See Delays)
- Time interval
between charts, 218, 223
between checks, 192
between cycles, 69, 162
between reports, 33, 224, 225
between samples, for inspection, 262, 274
required for processing, 71, 203, 218, 223
(See Intervals)
- Time lag, 218, 223
- Time for development of a quality control program, 33-34
- Time on the job, 72-73
(See Experience)
- Timing device, 70, 167, 180, 235
- Tin, 215
- Tired operator, inspector etc., 155, 162, 236
- Tolerances in the shop, 61-63, 202
(See Specifications; Statistical addition of tolerances; Natural tolerances)
- Tools
as a variable, 10, 55, 158, 168, 176, 224

- capability of, 35, 46
 changes in, 63, 175, 179
 comparison of, 46
 design of, 62, 121, 155, 169, 212, 219
 in need of maintenance, 162, 180
 inspection of, 227
 life of, 23
 modification of, 203, 212, 213, 219, 224
 suitability of, 203 (*See* Design; Re-design)
 wear of (*See* Toolwear)
- Toolwear**
 as a process variable, 10, 53, 61, 62, 150, 153, 162, 178, 220
- Torrey, M. N., 277
- "Total and range" charts, 197
- Total probability associated with statistical tests, 25 (footnote), 182, 183
- Totals (used in analysis), 81, 94, 197
- Tracing of cycles, 69, 70, 161-162
- Traffic conditions, 216
- Training**
 as a variable, 72-73, 203, 221
 for quality control, vii, 23, 33, 97
 of engineers, vii, 23, 33, 97
 of inspectors, 267-271
 of machine setters, 201, 203-204, 218
 of management, vii, 23, 33
 of members of the Quality control team, vii, 23, 33, 97, 223-224
 of operators, 30, 31, 35, 37, 46, 55, 72-73, 155, 158, 164, 167, 168, 169, 175, 180, 201, 203, 204, 212, 221
 of process checkers, 41, 192, 201, 205-209, 213-216, 217, 219, 224, 227
 of quality control engineers, vii, 23, 33, 97
 of shop people, vii, 201-202
 of statistical clerks, 228-229
 of supervisors, vii, 23, 33
- Training manuals, vii, 23, 97
 on quality rating, 264, 273, 278
- Trays, 214
- Trend arrangements, 56, 75
- Trends, 9, 10, 11, 29-30, 53, 54, 72, 152, 160-161, 170, 177-179
 as evidence of correlation, 143-144
 compared with "gradual change," 164
 estimating from, 55, 56, 60
 followed by operators, 203
 in defects, 159, 189
- Trial and error methods, 76, 77, 91-92
- Triangular distribution, 138
- Tripling of AOQL's, 273
- Trouble board for charts, 209, 218
- Troubles**
 associated with certain characteristics, 188
 at 450 cycles, 48
 beginnings of, in the shop, 37-38, 202, 217
 chronic, 10, 37-38, 188, 202
 diagnosis of, 11, 36, 188, 202, 217
 in meeting schedules, 37, 46, 226 (*See* Output; Delays)
 in the shop, 34, 35, 36-38, 187-188, 189-190, 219
 location of, 51, 188, 190, 202, 217-219
 (*See* Early operations)
 machine, 16, 48, 202, 203-204
 operations free from, 264
 operator, 16, 17, 30, 36, 48, 49, 55, 57, 61, 68, 70, 72-73, 152, 171, 178, 188-189, 203, 215, 217 (*See* Carelessness)
 periods of, in the shop, 187, 188, 202, 246, 273
 production, 11, 34, 35, 37-38, 46, 48, 66-72, 91, 122, 187-188, 217-219, 220, 224, 226, 273
 shown by control charts, 37-38, 202-206
 shown by patterns out of control, 189-190
 sources of, 46, 51, 187-188, 190, 202-206, 217-219, 220
 unknown causes of, 4, 10, 36, 48, 55, 68, 75, 188, 218, 219, 220
 unpredictable, 54, 187, 202
 with process, 66-72, 204, 206, 217-219, 220-221
 with specification, 122, 204, 205, 206
- Troughs, 162
- Trucking, 246, 261
- Truncation**
 of a distribution, 57-58, 141, 154
 of the inspection of a sample, 261
 of the taking of samples, 259
 (*See also* Sorting; Screening; Curtailed inspection)
- t-Test**
 for comparing averages, 78, 80, 82, 83
 for estimating percentage outside of limits, 58-59, 127, 132-133, 135-136
 for testing correlation coefficient, 146
- Tubes, 3, 4, 224, 225
- Tweezers, 168, 209
- "Twenty one hundred" organization, 224, 225
- Two-headed distribution**
 (*See* Bimodal)
- Two-sided tests, 107, 182
- Types of control chart, 10-11, 47-49, 188-189, 197-198
 of specifications, 119
- Typing, 3
- U**
- u, 21
- u-Charts, 21, 191
- Ultimate causes, 150, 166, 171
- Ultimate number of charts, 38, 189, 225
- Unanalyzed interactions, 168
- Unbalance, 24, 57 (*See* Balance)
- Unbiased samples**
 in a designed experiment, 85, 90, 93, 111, 113, 114-116, 116
 in a process capability study, 49, 50, 51, 52-53
 in sampling inspection, 239, 257, 260, 261, 262, 267-268, 269
 in the shop, 190, 192, 207, 209, 213-214, 215-216, 219, 227
- Underlying distribution (or universe), 6, 131, 137, 170, 171
 (*See* appropriate portions of pages 161-180)
- Uneconomical**
 inspection, 234, 246, 260-262, 273, 274
 requirements, 10, 34, 35, 36, 48, 62-63, 65, 187, 188
 results, from lack of control, 189, 217, 219, 233, 265, 273-274
 size of sample, 191, 260
- Unevenness of surface, 156, 168
- Unfinished**
 business, 120-121, 235-236
 capability studies, 36, 45, 47, 63, 66, 72-73, 75-76, 120
- Uniformity**
 in shop practices, 41, 192, 223, 227, 236
 of a process, 170, 175
 of material etc., 155, 167
 of random variation, 103
 shown by *R* chart, 30, 154
- Unimodal distributions**, 134-136, 170
 (*See* Normal distribution)
- Uninterpretable patterns, in a process capability study, 66-67
 (*See* Patterns)
- Union representatives, 202
- Unison, points moving in, 29, 156, 176-177
- United States Dept. of Defense, 278
- United States Dept. of Navy, 278
- United States Govt. Printing Office, 242, 247, 248, 275, 278
- Units**
 experimental, 163, 180
 group of, in a sample, 20, 191

- Units, *continued*
 number of, in a sample, 17, 18, 20, 66, 191 (*See* sample size)
 of product, 6, 153, 156, 163, 165, 172, 173, 175, 218
- Universe, 131, 137
 (*See* Sigma prime; Underlying distribution; Parent distribution)
- Unknown
 areas in research, 4
 causes of trouble, 10, 35, 38, 54-56, 66-68, 91-92, 155, 157, 159, 161, 166, 187, 188, 202, 217, 218, 219
 methods and processes, 34, 46-47
 value of sigma prime, 131
 variables (in engineering), 10, 33, 34, 35-36, 38, 51, 55, 75-76, 112, 220
- Unloading, 246
- Unnatural patterns
 analysis of, 9-10, 34, 35-36, 54-56, 66-72, 83, 87-89, 100-101, 161-180, 190, 217-219, 223
 background of tests for, 25 (footnote), 180-183
 characteristics of, 25
 complex, 54, 54-56
 importance of, 34-36, 47, 54, 168, 171, 194, 204, 217, 221
 information from, 11, 33, 35-36, 37, 54-56, 66-73, 83, 150-151, 159, 221
 list of, 11, 54, 161
 meaning of, 6, 9-10, 11, 16, 19-20, 25, 30-31, 35-38, 53, 54-56, 59-61, 66-72, 83, 87-89, 100-101, 107, 109, 112, 116-117, 149-180, 190, 196, 203-206, 208-209, 212-213, 215, 217-219, 223, 227, 229
 not necessarily undesirable, 35-36, 54, 150-151, 171
 simple, 54, 56, 72
 simplification of, 36, 53, 54-56, 66-70, 72-73, 75, 166, 179
 tests for, 23-30, 100-107, 109, 180-183
 (*See* Tests for unnatural patterns)
- Unnatural variation, 5-6, 9, 34-36, 37-38, 54-56, 159, 221
 (*See* Variability; Variation; Unnatural patterns)
- Unnecessary
 control charts, 38, 41, 189-190, 199, 219, 223, 227
 delays, 33, 187, 202, 217, 246, 262
 rejection, 246, 254-255, 264, 265, 273
 specifications or requirements, 36, 62, 65, 187, 188
- Unpredictability
 of an individual observation, 6-7
 (*See* Random fluctuations)
- of a process when out of control, 54, 59-61, 141, 219
 of trouble in the shop, 187, 188
- Unreasonable
 inspection plans, 246, 254-255, 261-263, 264
 number of causes, 190
 number of characteristics on p -chart, 17, 48, 59, 157, 159, 190
 number of items covered by sampling plan, 263
 relationships, 56, 146, 176
 specifications, 36, 48, 62-63, 65, 122, 125, 187, 188, 204 (*See* Changes)
 width of control limits, 73, 166, 172-173
- Unreliable
 averages, 60, 61, 83, 153, 154
 equipment, 180
 holding devices, 10, 69
- Unsatisfactory
 product, 217, 237-239, 244, 245, 262, 273
 suppliers, 39
- Unshaded boxes (or squares), 97, 106, 107, 110, 111
- Unsolved problems, 4, 38, 47, 52-53, 63, 75-76, 120-121, 188, 235-236
- Unstable
 equipment, 180
 patterns, in a breakdown of data, 55, 166
 patterns on a p -chart, 159
 product, 46, 90
 testing equipment, 156, 157, 178, 180
- Unstable mixtures
 analysis of, 55, 68-69, 166-167, 179-180
 elimination of, 68-69, 166
 importance of, 54, 68-69, 75, 155, 166, 179
 nature of, 54, 150, 166-167, 169-170, 179-180
 (*See* Mixtures)
- Unsuspected changes, 10, 55, 68, 114, 218
- Unsymmetrical control limits
 effect of, in testing for unnatural patterns, 28, 83, 182-183, 191
 on p -chart, 20, 28, 183, 191
 on R chart, 28, 83, 182-183, 191
 tests associated with, 182-183
- Unsymmetrical distributions, 134-136
 (*See* Skewness)
- Unsystematic procedures, 180
- Unwanted variables, 37, 77, 114
- Up-to-date
 audits, 41, 219, 223-224, 227
- plotting of shop charts, 208, 214, 227
 records, 189, 224-225, 227, 228
- Usability of charts, 190, 192, 199, 214-215, 219, 228
- User of product, 245, 246, 254, 264, 270

V

- Values used by clerks, 229
- Variability
 analysis of, in a designed experiment, 82-83, 85-89, 93, 94-97, 98-111, 168 (*See* Designed experiment; Residual)
 analysis of, on a control chart, 15-16, 19, 22-23, 23-30, 36, 37, 53-56, 59-61, 66-72, 72-73, 168, 180, 194, 203-206, 212-213, 218
 between measurements, 111 (*See* Error)
 comparison of, 78, 79-80, 83, 88-89, 93-97, 99 (*See* F -test; Bartlett's test; R chart)
 difference in, in portions of an experiment, 90, 111
 importance of, 5-7, 75, 90, 114, 153, 154-155, 168, 195, 218 (*See* R chart)
 meaning of, 5-7, 35, 75, 168
 measures of, 129-131
 of measurements, 87, 88, 89 (*See* Precision of measurement)
 of product (*See* Spread)
 positional, 89-90
 sources of, 35, 36, 54-56, 75-76, 92-93, 94, 98, 166, 168-169, 179, 187-188, 190, 218-219 (*See* Sources)
 total, 35, 45, 75-76, 80, 89, 93, 95, 123, 125
 (*See* Variation; Dispersion; Process spread)
- Variables acceptance plans
 (*See* Variables sampling)
- Variables (in an experiment)
 appearing in R chart, 83, 87-89, 100, 109
 appearing in \bar{X} chart, 83, 87, 89, 100
 held constant, 114
 identification of, 92, 99-100, 108-109
 interaction between, 36, 75, 77, 93, 94-96, 98, 99-101, 104-106, 107, 168-169
 introduction of, 92-93, 101-102
 randomizing of, 114-116
 removal of, 102-103, 105, 106
 selection of, 77, 89, 91, 92, 113-114
 selection of, for plotting, 99, 108

- simplification of, 106
studied in combination, 89-90, 93, 94-97, 100-101, 104-106
(See Interactions; Designed experiments)
- Variables (in a process)
analyzed in a process capability study, 66-72
comparison of, 4
covered by notes on a control chart, 53, 66-67, 208-209, 212-213, 215, 217, 221
definition of, for statistical clerks, 229
dependent, 145
elimination of, 37-38, 55, 66-68, 217, 219
erratic, 37, 69, 166-167, 179-180
importance of, 72
independent, 123, 145, 177
information on, 35, 36, 53, 54-56, 218, 221
interactions between, 167-169
knowledge of, 11, 16, 19-20, 34, 35, 49, 54, 55, 59, 157, 189, 202, 212-213, 215, 218-219, 221, 224-225
large, 6, 55, 69
masking effect of, 69, 169
ordinary, 71 (See Shop-type)
production, 35, 37, 38, 71
represented on a control chart, 72-73, 76, 149, 150-151
selection of, for simplifying patterns, 55, 66-68, 72
shop-type, 35, 37, 38, 71, 72, 212-213, 220
(See also Process elements; Job knowledge; Information)
- Variables control charts
examples of, 5, 8, 14, 15-16, 65, 67-71, 82, 85, 87-88, 99, 120-121, 203-206, 212
importance of, 11, 15-16, 47, 48, 188
where to use, 12, 48, 188
(See \bar{X} and R charts; Charts for individual measurements; Individual numbers)
- Variables data
advantages of, 11, 47-48, 113, 160, 188, 189, 218
examples of, 6, 8, 9, 10, 12, 14, 22, 78, 84, 86, 92, 137, 141, 144, 147
for a chart of individual measurements, 22-23, 160-161
for an \bar{X} and R chart, 12, 14, 15-16, 53-59, 66, 82, 86, 107-111, 152-156
substitutes for (semi-variables), 12, 49-50, 113
used for acceptance sampling (See Variables sampling plans)
- used in engineering studies, 48, 66-72, 119-127
used in shop charts, 65, 188, 191, 194, 195-198, 203-206, 209, 210, 212, 215, 225, 227-229
- Variables measurements, 6, 8, 12, 14, 21-22, 47, 78, 84, 92, 139, 147
(See Variables data)
- Variables sampling plans, 188, 242, 262, 265, 277
- Variance
additive property of, 49, 80-81, 89, 93, 95-97, 110, 124
analysis of (See Analysis of variance)
as a measure of spread, 124, 129, 130
calculation of, 130
components of, 80-81, 89, 95-97, 98
equivalence of, 78-80, 82, 83
sources of, 92-93, 94-97, 98, 101-106
(See also Variability; Standard deviation)
- Variance ratio
tables of, 79, 93, 277
tests for, 78, 79, 81, 96-97
- Variation in a process, 5-6, 35, 37, 53-54, 56, 61, 63, 64, 66, 72, 92, 137, 187-188, 203-206, 217-218, 220
initial, 35
natural or unnatural, 6, 9, 11, 24-25, 35-36, 37, 45, 75-76, 150
total, 35, 45, 75, 76, 80, 93, 95, 123, 125
(See Fluctuations; Variability)
- Varying size of sample, 18, 19, 20, 163, 180, 191
- Verification
of Operating results, 274
sampling, 268, 274
- Vertical welder, 213
- Visual
comparison of numbers, 78
impressions of changes, 10, 160, 161, 164, 178, 179, 190 (See Apparent)
- Visual checking, 4, 190, 209, 216, 268, 270
- Visual standards, 49-50, 216, 268
- Voltage, 21, 157, 162, 164
- Voltage range, 157
- Voltage regulator, 10
- Voltage supply, 48
- Volume of cubes, 57
- Wage incentives, 34, 46, 54, 202, 203, 224, 225, 226
(See Standards; Efficiency; Allowances)
- Walls, 192
- Warm-up of equipment, 37
- Warpage, 57, 113, 156, 167, 168
- Wash tank, 50
- Waste of time, 66, 77, 92, 246, 262
- Water for washing parts, 50
- Wear
of a bearing, 16
of a tool, 10, 53, 61, 62, 150, 153, 162, 178, 220
of guides and locators, 19
of lapping plates, 167
of threads, 10, 162
- Weaver, W. R., 101, 277
- Weekends, 37, 162, 189
- Weekly samples, 189, 191, 192
- Weeks
between samples, 192
data for, 189, 191
of service, 72, 73
- Weighted fraction defective, 198
- Welder, 209, 213
- Welding, 5, 7, 8, 9, 10, 11, 12, 57, 212, 213
- Western Electric Company, vii, 23, 25, 33, 91, 92, 93, 97, 100, 101, 122, 233, 254, 264, 267, 270, 278
- Westman, A. E., 101, 278
- Width
of a groove, 119
of control limits, 72, 73, 194
of control limits, in a designed experiment, 99-100, 107-109
standards of, 90
"Wild" units, 156
(See Freaks)
- Wilks, S. S., 278
- Winding tension, 153
- Wire, 4, 20, 162, 191, 209
- Wired equipment, 3-4, 17, 20-21, 191
- Wired panels, 20, 72-73, 191, 192
- "Within sample" causes, 150
- Work
done by machine setter, 203
interference with, 187, 202, 246
loads, 227
productive, 77, 246
saving of, 57, 77, 203
source of, 261
spoiled by operator, 214
waiting for, 50
- Workers, earnings of, 22
(See Operators)
- Work habits
of operators, 4, 10, 30, 38, 62, 72-73, 167, 202, 219
of people in the shop, 10, 50, 158, 188

W

- Wage incentive engineer, 50, 54, 56-61, 224, 225, 227, 235-236, 265, 273-274

Workmanship, 12
 Workmanship standards, 268
 Work patterns
 (See Work habits)
 Work sampling, 50
 Wrong
 conclusions, 49, 61, 66, 67, 77, 80,
 81, 84, 92, 112, 117, 125, 134,
 138, 141, 146, 153, 157, 159,
 160, 163, 166, 172, 175, 178,
 190, 194, 203-204
 distribution, 46, 119, 265
 setting, on a machine, 16, 188,
 202, 203, 217

X

\bar{X} , 12, 14, 21, 129
 \bar{X} , 12, 14
 \bar{X} and R charts
 action on, 16, 67-72, 203-204
 advantages of, 11, 16, 48, 113,
 189, 190, 198, 203-206
 amount of data required for (in
 engineering studies), 50, 52,
 90, 92
 analysis of, 66-72
 as a form of specification, 119
 as a measure of percentage, 56,
 58-59, 127
 as a measure of process capability,
 45, 46
 calculations for, 14
 centerline for, in the shop, 64,
 193-195, 195-196
 characteristics to be plotted on,
 12, 48, 188
 compared with p -charts, 11, 48-
 49, 113, 188-189, 190, 218
 compared with specification, 13,
 16, 30-31, 48, 54, 56, 58-59,
 61-63, 64-65, 71, 119-122,
 195, 196, 204-206
 construction of, 12-13
 control limits for, in the shop,
 194-195, 195-196
 data sheet for, 210
 examples of, 15-16, 65, 67-71, 82,
 85, 87, 88, 99, 120-121, 144,
 153-154, 203-206, 212

explanation of, 11, 152-156
 factors for, 12
 importance of, 11, 16, 48, 53-54,
 56, 58-59, 82, 83, 87-89, 100-
 101, 119-122, 126, 127, 131,
 144, 160, 189, 198
 in designed experiments, 82-83,
 84-89, 93-101, 107-109, 110-
 111, 113
 in engineering studies, 48, 50, 53-
 56, 58-59, 59-61, 64, 66-72
 interpretation of, 15-16, 30-31,
 53-56, 66-72, 83, 87-89, 100-
 101, 152-156, 190, 198, 203-
 206, 212, 218-219
 interpretation of, in a designed
 experiment, 100-101
 in the shop, 189-190, 203-206,
 212-213
 joint interpretation of, 16, 30-31,
 156, 176-177
 measurements for, 11, 12, 50, 113,
 198
 patterns on, 11, 53, 54-56, 83, 87,
 161-180
 plotting of, in a designed experi-
 ment, 99, 107-109
 proportion of, in the shop, 189,
 198, 225, 227
 samples for, in the shop, 191
 scales on, 13, 51
 sensitivity of, 11, 16, 48, 83, 189,
 218
 simplification of, 54-56, 66-72,
 166, 179
 substituted for a p -chart, 48, 113,
 198, 218
 substitutes for, 197-198
 symbols for, 12
 used for correlation, 144
 used for plotting percentage data,
 113, 198
 where to use in, general, 12, 48,
 188
 where to use, in the shop, 188
 \bar{X} chart
 causes on, different from R chart,
 11, 16, 48, 54-56, 66-71, 83,
 87-89, 100, 109, 153, 156,
 203-206 (See appropriate
 portions of pages 161-180)

construction of, 12-13
 control limits on, 13, 28, 138
 correlation on, 144, 156, 177
 cycles on, 69, 70,
 fluctuations on, 67, 69, 203, 206
 freaks on, 70, 163
 interaction on, 99, 168
 interpretation of, 16, 30-31, 66-
 71, 87, 89, 91, 100, 109, 152-
 154, 170, 203-204
 interpretation of, in an error of
 measurement study, 87-89, 91
 method of indicating specified
 limits on, 13, 30-31, 190 (See
 Arrows)
 mixtures on, 171, 179
 substitutes for, 197-198
 tests for, 109, 180-182
 theory of, 137-138, 151
 variables appearing in, 100, 109
 "X" charts, 198
 \bar{X} points
 calculation of, 12, 14, 82, 86, 109,
 162, 215
 in a designed experiment, 109
 x 's
 importance of, 23, 25, 27, 52, 168,
 195, 218
 marking of (See Marking x 's.)
 on the low side of an R chart, 67,
 70, 166, 168, 195
 showing clarity of pattern, 67-68

Y

Yates, F., 101, 277
 Yields, 4, 10, 31, 46, 61, 62, 91, 92,
 101, 121, 157, 189, 193, 217,
 225
 (See Losses)
 Yule, G. U., 278

Z

Zero correlation, 146
 Zero variation, 101-103, 104, 105,
 171
 Zig-zag pattern, 5, 23, 237-238
 Zone tests, 25-30, 180-18

